

DEPARTMENT OF TRANSPORTATION
 DIVISION OF ENGINEERING SERVICES
 Office of Structural Materials
 Quality Assurance and Source Inspection



Bay Area Branch
 690 Walnut Ave. St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493

Contract #: 04-0120F4
 Cty: SF/ALA Rte: 80 PM: 13.2/13.9
 File #: 69.25B

QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

Location: Changxing Island, Shanghai, PRC **Report No:** NCR-000175
Prime Contractor: American Bridge/Fluor Enterprises, a JV **Date:** 18-Aug-2008
Submitting Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **NCR #:** ZPMC-0158



Type of problem:

Welding	Concrete	Other	
Welding	Curing	Procedural	Bridge No: 34-0006
Joint fit-up	Coating	Other	Component: Tower
Procedural	Procedural	Descriptor: NSD1-SA322-B/B-3 & 4	

Reference Description: Unqualified Welder


Description of Non-Conformance:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhu) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.



QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

(Continued Page 2 of 2)



Applicable reference:

AWS D1.5-2002, Section 5.22.1, Table 5.6

Who discovered the problem: Quality Assurance (QA) Inspector, Kenneth Riley

Name of individual from Contractor notified: ABFJV Quality Control Inspector, Mike Williams

Time and method of notification: 18-AUG-08, Via phone @ approximately 2030hrs

Name of Caltrans Engineer notified: Scott Kennedy, Structure Representative

Time and method of notification: 21-AUG-08, at approximately 1330 hours

QC Inspector's Name: Xu Jun (Erick)

Was QC Inspector aware of the problem: Yes No

Contractor's proposal to correct the problem:

Comments:

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, who represents the Office of Structural Materials for your project.

Inspected By: Smith,Ryan

SMR

Reviewed By: Smith,Ryan

SMR



DEPARTMENT OF TRANSPORTATION - District 4 Toll Bridge
 333 Burma Road
 Oakland CA 94607
 Tel: Fax:

NON-CONFORMANCE REPORT TRANSMITTAL

To: AMERICAN BRIDGE/FLUOR, A JV
 375 BURMA ROAD
 OAKLAND CA 95607

Date: 22-Aug-2008

Contract No: 04-0120F4
 04-SF-80-13.2 / 13.9

Dear: Mr. Charles Kanapicki
Attention: Mr. Dave Williams Consultant
Subject: NCR No. ZPMC-0158

Job Name: SAS Superstructure
Document No: 05.03.06-000147

Reference Description: Unqualified Welder / Double Diaphragm

The attached Non-Conformance Report describes an occurrence where the contractor did not comply with a requirement of the contract document as indicated below:

- Material or Workmanship not in conformance with contract documents.
- Quality Control (QC) not performed in conformance with contract documents.
- Recurring QC issue that constitutes a systematic problem in quality control.
- Non-Conformance Resolved.

Material Location: Tower **Lift:** 01

Remarks:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhu) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.

Action Required and/or Action Taken:

Propose a resolution for the identified non-conformance that documenting that the weld placed is in compliance with the contract requirements. In addition to the material/workmanship non-conformance, propose a resolution for the identified non-conformance that addresses the failure of Quality Control to identify the lack of welder qualification for the weld position and once the lack of the qualification was identified to allow the welder to continue. Provide documentation of the steps taken by the Quality Control Manager to prevent future occurrences.

Transmitted by: Scott Kennedy Sr. Bridge Engineer

Attachments: ZPMC-0158

cc: Rick Morrow, Gary Pursell, Mark Woods, Doug Coe

File: 05.03.06

NCR PROPOSED RESOLUTION

To: CALTRANS - SAS Superstructure
333 Burma Road
Oakland CA 94607

Attention: Pursell, Gary
Resident Engineer

Ref: 05.03.06-000147

Subject: NCR No. ZPMC-0158

Dated: 11-Sep-2008

Contract No.: 04-0120F4
04-SF-80-13.2 / 13.9

Job Name: SAS Superstructure

Document No.: ABF-NPR-000146 **Rev:** 00

Contractor's Proposed Resolution:

Reference Resolution: ZPMC specifically assigned the welder to this weld as he is certified in the 4G position.

ZPMC takes exception to this NCR as this weld is shown to be in the 4G position per AWS D1.5 figure 5.5 position C. ZPMC specifically assigned the welder to this weld as he is certified in the 4G position.

Submitted by:

Attachment(s): ABF-NPR-000146R00

Caltrans' comments:

Status: CLO

Date: 29-Sep-2008

The Contractor's response is acceptable. After further discussion, the weld in question is in the 4G position, and the welder was qualified in that position. The Department concurs that Non-Conformance ZPMC-0158 is closed.

Submitted by: Wright, Doug

Date: 29-Sep-2008

Attachment(s):

NCR PROPOSED RESOLUTION

To: CALTRANS - SAS Superstructure
333 Burma Road
Oakland CA 94607

Attention: Pursell, Gary
Resident Engineer

Ref: 05.03.06-000147

Subject: NCR No. ZPMC-0158

Dated: 24-Sep-2008

Contract No.: 04-0120F4
04-SF-80-13.2 / 13.9

Job Name: SAS Superstructure

Document No.: ABF-NPR-000146 **Rev:** 01

Contractor's Proposed Resolution:

Reference Resolution: ZPMC takes exception to this NCR, ZPMC specifically assigned the welder to this weld as he is certified in the 4G position.

ZPMC takes exception to this NCR as this weld is shown to be in the 4G position per AWS D1.5 figure 5.5 position C. ZPMC specifically assigned the welder to this weld as he is certified in the 4G position. Please see additional attached data.

Submitted by:

Attachment(s): ABF-NPR-000146R01;

Caltrans' comments:

Status: CLO

Date: 29-Sep-2008

The Contractor's response is acceptable. After further discussion, the weld in question is in the 4G position, and the welder was qualified in that position. The Department concurs that Non-Conformance ZPMC-0158 is closed.

Submitted by: Wright, Doug

Date: 29-Sep-2008

Attachment(s):



TRANSMITTAL LETTER

PROJECT: SAN FRANCISCO OAKLAND BAY BRIDGE

DATE: 09/12/2008

TO: RUBY/ ABFJV QA DEPARTMENT

FROM: ZPMC QA DEPARTMENT

SUBJECT: NCR-000175(ZPMC-0158)FOR CLOSURE

SUBMITTED FOR YOUR APPROVAL.

ENCLOSED WITH THIS TRANSMITTAL IS ONE

- (1) COPY OF LETTER OF RESPONSE WITH NO.T-017.
- (2) COPY OF NCR WITH NUMBER NCR-000175(ZPMC-0158)
- (3) COPY OF WPS-B-T-33(1)14.

PLEASE SIGN THIS TRANSMITTAL AND RETURN TO ME.

ACKNOWLEDGEMENT:

Prin
PLAN HOLDER

9/12/08 1435
DATE

ABFJV
COMPANY

PHONE NO.

PLAN NUMBER: N/A
#R787-QCP-102



No. T-017

LETTER OF RESPONSE

TO: American Bridge/Flour JV

DATE: 2008-9-12

REGARDING: NCR-000175 (ZPMC-0158)

ZPMC received Caltrans' NCR-000158, it mentioned ZPMC welded on the Tower component number NSD1-SA322B/B-3&4(Double diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC QC was informed of this discrepancy, the welder was allowed by Mr.Xu Jun to perform welding again in the same position and weld joint.

ZPMC took exception to this NCR. ZPMC arranged the 4G (4F) welder to perform the tack welding in the overhead position, which CT inspector Kenneth Riley regarded as the horizontal position. But ZPMC looked into the AWS chapter 5 figure 5.5, and joint WT 65 & WT 66. ZPMC is pretty sure the position the welder performed in is the overhead position. So ZPMC did not commit any mistake as to this NCR. Please see the attached sketch and WPS for your reference.

So ZPMC hoped Caltrans can check again and withdraw this NCR.

ATTACHMENT:

NCR-000175 (ZPMC-0158)

WPS-B-T-33(1)14

Xu Jun 2008.9.12

[Handwritten signature]
ABF QCM
16 SEPT. 08



DEPARTMENT OF TRANSPORTATION - District 4 Toll Bridge
333 Burma Road
Oakland CA 94607
Tel: Fax:

NON-CONFORMANCE REPORT TRANSMITTAL

To: AMERICAN BRIDGE/FLUOR, A JV
375 BURMA ROAD
OAKLAND CA 95607

Date: 22-Aug-2008

Contract No: 04-0120F4
04-SF-80-13.2 / 13.9

Job Name: SAS Superstructure

Document No: 05.03.06-000147

Dear: Mr. Charles Kanapicki

Attention: Mr. Dave Williams Consultant

Subject: NCR No. ZPMC-0158

Reference Description: Unqualified Welder / Double Diaphragm

The attached Non-Conformance Report describes an occurrence where the contractor did not comply with a requirement of the contract document as indicated below:

- Material or Workmanship not in conformance with contract documents.
- Quality Control (QC) not performed in conformance with contract documents.
- Recurring QC issue that constitutes a systematic problem in quality control.
- Non-Conformance Resolved.

Material Location: Tower

Lift: 01

Remarks:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhui) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.

Action Required and/or Action Taken:

Propose a resolution for the identified non-conformance that documenting that the weld placed is in compliance with the contract requirements. In addition to the material/workmanship non-conformance, propose a resolution for the identified non-conformance that addresses the failure of Quality Control to identify the lack of welder qualification for the weld position and once the lack of the qualification was identified to allow the welder to continue. Provide documentation of the steps taken by the Quality Control Manager to prevent future occurrences.

Transmitted by: Scott Kennedy Sr. Bridge Engineer

Attachments: ZPMC-0158

cc: Rick Morrow, Gary Pursell, Mark Woods, Doug Coe

File: 05.03.06

02.02;15.04

05.03.06-000147_NCT

Received
NCT-000147 22 Aug 08

DEPARTMENT OF TRANSPORTATION
DIVISION OF ENGINEERING SERVICES
 Office of Structural Materials
 Quality Assurance and Source Inspection



Bay Area Branch
 690 Walnut Ave. St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493

Contract #: 04-0120F4
 Cty: SF/ALA Rte: 80 PM: 13.2/13.9
 File #: 69.25B

QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

Location: Changxing Island, Shanghai, PRC

Report No: NCR-000175

Prime Contractor: American Bridge/Fluor Enterprises, a JV

Date: 18-Aug-2008

Submitting Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island

NCR #: ZPMC-0158



Type of problem:

Welding Concrete Other
 Welding Curing Procedural Bridge No: 34-0006
 Joint fit-up Coating Other Component: Tower
 Procedural Procedural Descripton: NSD1-SA322-B/B-3 & 4

Reference Description: Unqualified Welder


Description of Non-Conformance:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhua) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.



QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

(Continued Page 2 of 2)



Applicable reference:

AWS D1.5-2002, Section 5.22.1, Table 5.6

Who discovered the problem: Quality Assurance (QA) Inspector, Kenneth Riley

Name of individual from Contractor notified: ABFJV Quality Control Inspector, Mike Williams

Time and method of notification: 18-AUG-08, Via phone @ approximately 2030hrs

Name of Caltrans Engineer notified: Scott Kennedy, Structure Representative

Time and method of notification: 21-AUG-08, at approximately 1330 hours

QC Inspector's Name: Xu Jun (Erick)

Was QC Inspector aware of the problem: Yes No

Contractor's proposal to correct the problem:

Comments:

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, who represents the Office of Structural Materials for your project.

Inspected By: Smith,Ryan

SMR

Reviewed By: Smith,Ryan

SMR



焊接工艺规程 B*
WELDING PROCEDURE SPECIFICATION

编号 No. WPS-B-T-33(1)14
(定位焊 tack weld)
有效期 Period of validity
FCM: 2007.5~2010.5
NON-FCM: 2007.5~2012.5

母材技术条件 (Material specification) A.709M HPS 485WT2/SHEAR LINK GRADE 485
 焊接方法 (Welding process) 药皮焊条手工电弧焊(SMAW)
 手工或机械 (Manual or machine or semi-auto) 手工(Manual)
 焊接位置 (Position of welding) 仰焊(4G4F)
 填充金属技术条件 (Filler metal specification) AWS A5.5 填充金属级别 (Filler metal classification) E9018M
 填充金属牌号 (Filler metal brand) Excalibur 9018M MR (Φ4.0)
 焊剂 (Flux) N/A
 保护气体 (Shielding gas) N/A 流率 (Flow rate) N/A
 单焊道或多焊道 (Single or multiple pass) 多道(Multiple Pass)
 单弧或多弧 (Single or multiple arc) 单弧(Single arc)
 焊接电流 (Welding current) 直流(DC) 极性 (Polarity) 反接(EP)
 焊丝伸出长度 (Electrode extension) N/A
 焊接方向 (Welding progression) N/A
 根部处理 (Root treatment) N/A
 焊前最低预热温度和道间温度 (Minimum preheat and interpass temperature before welding) 40°C [T≤20mm] 100°C [20mm<T≤40mm] 140°C [40mm<T≤60mm] 180°C [60mm<T≤100mm]
 最高预热和道间温度 (Preheat and interpass temperature Max) 230°C
 后热温度(Postheat temperature) N/A
 热输入 (线能量) (Heat input) 最小(Min) 1.53KJ/mm
 焊接工艺 (Welding procedure)

APPROVED
 APPROVED AS NOTED
 NOT APPROVED

Pursuant to Section 5-1.02 of the Standard Specifications of the State of California
 DEPARTMENT OF TRANSPORTATION

Signed [Signature]
 Structure Representative

Date 10-1-2007

焊道序号 Pass No.	焊条(丝)规格 Electrode Size (mm)	焊接电流 Welding Current		焊接速度 Travel Speed (mm/min)	接头详图 Joint Detail
		安培 Amp(s)	伏特 Volts		
1~n	4.0	130~210	20~28	64.7~230.6	该 WPS 用于已批准的符合 AWS D1.5-2002 图 2.4 和图 2.5 的焊接坡口。 This WPS is to be used for all preapproved WPSs weld joints as identified in accordance with Figures 2.4 and 2.5 of AWS D1.5M/D1.5---2002 Edition.

选定适用的电流、电压后在 WPS 焊接参数选用表中查到焊接速度范围。
Refer to WPS parameters table to determine operating parameter to stay within the heat input limit.

该工艺可以因制造工序、装配、焊道尺寸等而变化, 但应在 AASHTO/AWS D1.5 第 5 章给出的变量限值之内。
(This procedure may vary due to fabrication sequence, fit-up, pass size, etc., within the limitation of variables given in section 5.)

修订号(Revision No.) 0

工艺评定记录编号(PQR No.) HP200778-1/HP200781-1

* 本 WPS 符合 AASHTO/AWS D1.5 2002, 用于桥梁结构。

(This WPS is conformable with the current edition of AASHTO/AWS D1.5 2002, used for BRIDGE structure.)

批准(Authorized by) [Signature]
日期(Date) 2007 9.20

注: 该 WPS 仅适用于定位焊。 Note: This WPS is used for the tack welds.



焊接参数选用表 B*
SELECTED LIST OF WELDING
PARAMETER

编号 No.
WPS-B-T-33(1)14
(定位焊 tack weld)

PQR 编号: HP200778-1

PQR No.

对于免除评定 $\Phi 4.0$ 焊条 WPS

For WPS Prequalified For SMAW $\Phi 4.0$ Electrode

	电流 Amps	电压 Volts	焊接速度	热输入						
			Travel Speed (mm/min)	Heat Input (KJ/mm)						
平均值 Average										
范围 Range										
最大值 Maximum	210.0	28.0		2.41						
最小值 Minimum	130.0	20.0		1.53						

WPS 焊接参数选用表
WPS Parameters Table

电压 Volts	电流 Amps									
	130.0	150.0	170.0	190.0	210.0					
20.0	64.7	102.0	74.7	117.6	84.6	133.3	94.6	149.0	104.6	164.7
22.0	71.2	112.2	82.2	129.4	93.1	146.7	104.1	163.9	115.0	181.2
22.7	73.4	115.6	84.6	133.3	95.9	151.1	107.2	168.9	118.5	186.7
26.0	84.1	132.5	97.1	152.9	110.0	173.3	123.0	193.7	135.9	214.1
28.0	90.6	142.7	104.6	164.7	118.5	186.7	132.4	208.6	146.4	230.6

焊接速度 Travel Speed in mm/min

选用示例: 如选用 170A 和 22V, 在表中纵横相交查到的焊接速度范围为 93.1~146.7mm/min.

X.:170A×22V×Travel speed Range 93.1~146.7mm/min.

- APPROVED
- APPROVED AS NOTED
- NOT APPROVED


Pursuant to Section 5-1.02
of the Standard Specifications
State of California
DEPARTMENT OF TRANSPORTATION

Signed *Rick McRae*
Structure Representative

Date 10-1-2007

批准(Authorized By): *周瑞平*


日期(Date): 2007-9-20



WT65 & WT46


(1)

Sketch :



Inclination of weld axis is 0° .

(2)



(3)

— overhead range

NCR PROPOSED RESOLUTION

To: CALTRANS - SAS Superstructure
333 Burma Road
Oakland CA 94607

Attention: Pursell, Gary
Resident Engineer

Ref: 05.03.06-000147

Subject: NCR No. ZPMC-0158

Dated: 01-Oct-2008

Contract No.: 04-0120F4
04-SF-80-13.2 / 13.9

Job Name: SAS Superstructure

Document No.: ABF-NPR-000146 **Rev:** 02

Contractor's Proposed Resolution:

Reference Resolution: ZPMC takes exception with this NCR and the position of the weld.

Please find attached.

Submitted by:

Attachment(s): ABF-NPR-000146R02;

Caltrans' comments:

Status: CLO

Date: 10-Oct-2008

Per the attached email from Kim Mackey of ABF, ABF-NPR-000146R02 has been retracted. The response to ABF-ZPMC-000146R01 reads as follows and closes NCR No. ZPMC-0158.

"The Contractor's response is acceptable. After further discussion, the weld in question is in the 4G position, and the welder was qualified in that position. The Department concurs that Non-Conformance ZPMC-0158 is closed."

Submitted by: Prchlik, Aaron

Date: 10-Oct-2008

Attachment(s): Attached Email

DEPARTMENT OF TRANSPORTATION

CHINA FABRICATION TEAM
 506 Shangcheng Rd., Pudong New District
 Shanghai 200120, PRC



REVIEW OF CONTRACTOR'S TRANSMITTAL

To: Dave Williams, American Bridge – Fluor, a Joint Venture
Gary Pursell, Resident Engineer

Review Date: 09/30/2008

From: Joshua Ishibashi, Structural Materials Representative

Contract No.: 04-0120F4

Date/Time Submittal Received: 09/16/2008

China Standard Time
 (GMT+08:00)

Contractor's Transmittal #: AFC-CAL-TRN-001326

Rev. # 0

<input checked="" type="checkbox"/>	substantially complies with contract requirements and is approved		
<input type="checkbox"/>	substantially complies with contract requirements and is approved as noted.		
<input type="checkbox"/>	Lacks sufficient information and/or contains unacceptable items that must be corrected or prior to resubmital		
Verbal Notification	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	Date: _____ Time: _____
Name of individual from Contractor Notified: _____			
This submittal is a:	<input type="checkbox"/> Welding Report	<input type="checkbox"/> Critical Weld Repair	
	<input type="checkbox"/> Request for Information	<input type="checkbox"/> Heat Straightening Request	
	<input type="checkbox"/> Fabrication Procedures	<input checked="" type="checkbox"/> Other: NCR Closure	
Submitting Contractor: <u>ZPMC</u>			
ITEMS REVIEWED	COMPLIES		COMMENTS
1. NCR ZPMC-0158	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	See Remarks
2.	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
3.	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
4.	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
5.	<input type="checkbox"/> Yes	<input type="checkbox"/> No	

Remarks: METS recommends that AFC-CAL-TRN-001326 be approved and this NCR be closed.


JII

Reviewer: Joshua Ishibashi

Date: 09/30/2008

Construction Concurrence: Initials DLW Date 2008-09-30

Received by (ABFJV): DL Date 9-30-08 Time 1005



PROJECT: SAN FRANCISCO OAKLAND BAY BRIDGE

DATE: 09/12/2008

TO: RUBY/ ABFJV QA DEPARTMENT

FROM: ZPMC QA DEPARTMENT

SUBJECT: NCR-000175(ZPMC-0158)FOR CLOSURE

SUBMITTED FOR YOUR APPROVAL.

ENCLOSED WITH THIS TRANSMITTAL IS ONE

- (1) COPY OF LETTER OF RESPONSE WITH NO.T-017.
- (2) COPY OF NCR WITH NUMBER NCR-000175(ZPMC-0158)
- (3) COPY OF WPS-B-T-33(1)14.

PLEASE SIGN THIS TRANSMITTAL AND RETURN TO ME.

ACKNOWLEDGEMENT:

[Signature]

 PLAN HOLDER

9/12/08 1435

 DATE

ABFJV

 COMPANY

PLAN NUMBER: N/A
 #R787-QCP-102

PHONE NO. _____

APPROVED

APPROVED AS NOTED

RETURNED FOR CORRECTION

Pursuant to Section 5-1.02
 of the Standard Specifications
 State of California

DEPARTMENT OF TRANSPORTATION
 Division of Engineering Service
 Office of Structure Construction

Structure Representative _____

DW for RM 2008-09-30



No. T-017

LETTER OF RESPONSE

TO: American Bridge/Flour JV

DATE: 2008-9-12

REGARDING: NCR-000175 (ZPMC-0158)

ZPMC received Caltrans' NCR-000158, it mentioned ZPMC welded on the Tower component number NSD1-SA322B/B-3&4(Double diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC QC was informed of this discrepancy, the welder was allowed by Mr.Xu Jun to perform welding again in the same position and weld joint.

ZPMC took exception to this NCR. ZPMC arranged the 4G (4F) welder to perform the tack welding in the overhead position, which CT inspector Kenneth Riley regarded as the horizontal position. But ZPMC looked into the AWS chapter 5 figure 5.5, and joint WT 65 & WT 66. ZPMC is pretty sure the position the welder performed in is the overhead position. So ZPMC did not commit any mistake as to this NCR. Please see the attached sketch and WPS for your reference.

So ZPMC hoped Caltrans can check again and withdraw this NCR.

ATTACHMENT:

NCR-000175 (ZPMC-0158)

WPS-B-T-33(1)14

Xu Jun 2008.9.12

<input checked="" type="checkbox"/>	APPROVED
<input type="checkbox"/>	APPROVED AS NOTED
<input type="checkbox"/>	RETURNED FOR CORRECTION
Pursuant to Section 5-1.02	
of the Standard Specifications	
State of California	
DEPARTMENT OF TRANSPORTATION	
Division of Engineering Service	
Office of Structure Construction	
Structure Representative	Date

DCW for PM

2008-09-30

*ASB QCM
16 SEPT. 08*



DEPARTMENT OF TRANSPORTATION - District 4 Toll Bridge
 333 Burma Road
 Oakland CA 94607
 Tel: Fax:

NON-CONFORMANCE REPORT TRANSMITTAL

To: AMERICAN BRIDGE/FLUOR, A JV
 375 BURMA ROAD
 OAKLAND CA 95607

Date: 22-Aug-2008
 Contract No: 04-0120F4
 04-SF-80-13.2 / 13.9

Dear: Mr. Charles Kanepicki
 Attention: Mr. Dave Williams Consultant
 Subject: NCR No. ZPMC-0158

Job Name: SAS Superstructure
 Document No: 05.03.06-000147

Reference Description: Unqualified Welder / Double Diaphragm

The attached Non-Conformance Report describes an occurrence where the contractor did not comply with a requirement of the contract document as indicated below:

- Material or Workmanship not in conformance with contract documents.
- Quality Control (QC) not performed in conformance with contract documents.
- Recurring QC issue that constitutes a systematic problem in quality control.
- Non-Conformance Resolved.

Material Location: Tower

Lift: 01

Remarks:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jihu) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.

Action Required and/or Action Taken:

Propose a resolution for the identified non-conformance that documenting that the weld placed is in compliance with the contract requirements. In addition to the material/workmanship non-conformance, propose a resolution for the identified non-conformance that addresses the failure of Quality Control to identify the lack of welder qualification for the weld position and once the lack of the qualification was identified to allow the welder to continue. Provide documentation of the steps taken by the Quality Control Manager to prevent future occurrences.

Transmitted by: Scott Kennedy Sr. Bridge Engineer

Attachments: ZPMC-0158

cc: Rick Morrow, Gary Pursell, Mark Woods, Doug Coe

File: 05.03.06

02.02;15.04

05.03.06-000147,NCT

Received
 NCT-000147 22 Aug 08

DEPARTMENT OF TRANSPORTATION
DIVISION OF ENGINEERING SERVICES
 Office of Structural Materials
 Quality Assurance and Source Inspection

Bay Area Branch
 690 Walnut Ave. St. 150
 Vallejo, CA 94592-1133
 (707) 649-5453
 (707) 649-5493



Contract #: 04-0120F4
 Cty: SF/ALA Rte: 80 PM: 13.2/13.9
 File #: 69.25B

QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

Location: Changxing Island, Shanghai, PRC

Report No: NCR-000175

Prime Contractor: American Bridge/Fluor Enterprises, a JV

Date: 18-Aug-2008

Submitting Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island

NCR #: ZPMC-0158



Type of problem:

Welding Concrete Other
 Welding Curing Procedural Bridge No: 34-0006
 Joint fit-up Coating Other Component: Tower
 Procedural Procedural Description: NSD1-SA322-B/B-3 & 4

Reference Description: Unqualified Welder


Description of Non-Conformance:

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhu) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.



QUALITY ASSURANCE -- NON-CONFORMANCE REPORT

(Continued Page 2 of 2)



Applicable reference:

AWS D1.5-2002, Section 5.22.1, Table 5.6

Who discovered the problem: Quality Assurance (QA) Inspector, Kenneth Riley

Name of individual from Contractor notified: ABFJV Quality Control Inspector, Mike Williams

Time and method of notification: 18-AUG-08, Via phone @ approximately 2030hrs

Name of Caltrans Engineer notified: Scott Kennedy, Structure Representative

Time and method of notification: 21-AUG-08, at approximately 1330 hours

QC Inspector's Name: Xu Jun (Erick)

Was QC Inspector aware of the problem: Yes No

Contractor's proposal to correct the problem:

Comments:

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, who represents the Office of Structural Materials for your project.

Inspected By: Smith,Ryan

SMR

Reviewed By: Smith,Ryan

SMR

	焊接工艺规程 B* WELDING PROCEDURE SPECIFICATION	编号 No. WPS-B-T-33(1)14 (定位焊 tack weld)
		有效期 Period of validity FCM: 2007.5~2010.5 NON-FCM: 2007.5~2012.5

母材技术条件 (Material specification) A.709M HPS 485WT2/SHEAR LINK GRADE 485

焊接方法 (Welding process) 药皮焊条手工电弧焊(SMAW)

手工或机械 (Manual or machine or semi-auto) 手工(Manual)

焊接位置 (Position of welding) 仰焊(4G4F)

填充金属技术条件 (Filler metal specification) AWS A5.5 填充金属级别 (Filler metal classification) E9018M

填充金属牌号 (Filler metal brand) Excalibur 9018M MR (Φ4.0)

焊剂 (Flux) N/A

保护气体 (Shielding gas) N/A 流率 (Flow rate) N/A

单焊道或多焊道 (Single or multiple pass) 多道(Multiple Pass)

单弧或多弧 (Single or multiple arc) 单弧(Single arc)

焊接电流 (Welding current) 直流(DC) 极性 (Polarity) 反接(RP)

焊丝伸出长度 (Electrode extension) N/A

焊接方向 (Welding progression) N/A

根部处理 (Root treatment) N/A

焊前最低预热温度和道间温度 (Minimum preheat and interpass temperature before welding) 40°C [T≤20mm] 100°C [20mm<T≤40mm] 140°C [40mm<T≤60mm] 180°C [60mm<T≤100mm]

最高预热和道间温度 (Preheat and interpass temperature Max) 230°C

后热温度(Postheat temperature) N/A

热输入 (线能量) (Heat input) 最小(Min) 1.53KJ/mm

焊接工艺
(Welding procedure)

APPROVED
 反接(RP)
 APPROVED AS NOTED
 NOT APPROVED

Pursuant to Section 5-1.02
of the Standard Specifications
State of California
DEPARTMENT OF TRANSPORTATION

Signed [Signature]
Structure Representative

Date 10-1-2007

焊道序号 Pass No.	焊条(丝)规格 Electrode Size (mm)	焊接电流 Welding Current			焊接速度 Travel Speed (mm/min)	接头详图 Joint Detail
		安培 Amp(s)	伏 Volts	特		
1~n	4.0	130~210	20~28		64.7~230.6	该 WPS 用于已批准的符合 AWS D1.5-2002 图 2.4 和图 2.5 的焊接坡口。 This WPS is to be used for all preapproved WPSs weld joints as identified in accordance with Figures 2.4 and 2.5 of AWS D1.5M/D1.5---2002 Edition.

选定适用的电流、电压后在 WPS 焊接参数选用表中查到焊接速度范围。
Refer to WPS parameters table to determine operating parameter to stay within the heat input limit.

该工艺可以因制造工序、装配、焊道尺寸等而变化, 但应在 AASHTO/AWS D1.5 第 5 章给出的变量限值之内。
(This procedure may vary due to fabrication sequence, fit-up, pass size, etc., within the limitation of variable given in section 5.)

修订号(Revision No.) 0 批准(Authorized by) [Signature]

工艺评定记录编号(PQR No.) HP200778-1/HP200781-1 日期(Date) 2007.9.20

* 本 WPS 符合 AASHTO/AWS D1.5 2002, 用于桥梁结构。
(This WPS is conformable with the current edition of AASHTO/AWS D1.5 2002, used for BRIDGE structure.)

注: 该 WPS 仅适用于定位焊。 Note: This WPS is used for the tack welds.



焊接参数选用表 B*
SELECTED LIST OF WELDING
PARAMETER

编号 No.
WPS-B-T-33(1)14
(定位焊 tack weld)

PQR 编号: HP200778-1
PQR No.

对于免除评定Φ4.0 焊条 WPS
For WPS Prequalified For SMAW Φ4.0 Electrode

	电流 Amps	电压 Volts	焊接速度 Travel Speed	热输入 Heat Input						
			(mm/min)	(KJ/mm)						
平均值 Average										
范围 Range										
最大值 Maximum	210.0	28.0		2.41						
最小值 Minimum	130.0	20.0		1.53						

WPS 焊接参数选用表
WPS Parameters Table

电压 Volts	电流 Amps									
	130.0		150.0		170.0		190.0		210.0	
20.0	64.7	102.0	74.7	117.6	84.6	133.3	94.6	149.0	104.6	164.7
22.0	71.2	112.2	82.2	129.4	93.1	146.7	104.1	163.9	115.0	181.2
22.7	73.4	115.6	84.6	133.3	95.9	151.1	107.2	168.9	118.5	186.7
26.0	84.1	132.5	97.1	152.9	110.0	173.3	123.0	193.7	135.9	214.1
28.0	90.6	142.7	104.6	164.7	118.5	186.7	132.4	208.6	146.4	230.6

焊接速度 Travel Speed in mm/min

选用示例: 如选用 170A 和 22V, 在表中纵横相交查到的焊接速度范围为 93.1~146.7mm/min.

X.:170A×22V×Travel speed Range 93.1~146.7mm/min.

APPROVED
 APPROVED AS NOTED
 NOT APPROVED

Pursuant to Section 5-1.02
of the Standard Specifications
State of California
DEPARTMENT OF TRANSPORTATION

Signed *Richard P. Morrow*
Structure Representative

Date 10-1-2007

批准(Authorized By): *[Signature]*

日期(Date): 2007.9.20



"Kim Mackey"
<kmackey@abfjv.com>
10/03/2008 11:54 AM

To ""Kim Mackey"" <kmackey@abfjv.com>,
<lsoononn@abfjv.com>, <slawton@abfjv.com>,
<apeterson@abfjv.com>, <ckanapicki@abfjv.com>,
cc <awong@abfjv.com>

bcc

Subject Retracting: ABF-CAL ABF-NPR-000146R2 - ZPMC 158

Sorry, I got in too much of a rhythm and sent this in accidentally. It is here by retracted as the Original and Rev. 1 are closed.

My apologies!

Kim Mackey

From: Kim Mackey [mailto:kmackey@abfjv.com]

Sent: Wednesday, October 01, 2008 12:57 PM

To: (lsoononn@abfjv.com); (slawton@abfjv.com); apeterson@abfjv.com; ckanapicki@abfjv.com; cknops@abfjv.com; Dan Raynor; Dave Williams; Dave Williams (dwilliams@abfjv.com); draynor@abfjv.com; dwalton@cn.abfjv.com; fzhang@abfjv.com; Gang jiao; gjiao@abfjv.com; grosamilia@abfjv.com; JBowers@abfjv.com; MFlowers@abfjv.com; Nate Lindell; nlindell@abfjv.com; Peter Ferguson; Ruby Li (rli@abfjv.com); Sbuschmeyer@abfjv.com; Thomas Nilsson; TNilsson@abfjv.com; wyang@cn.abfjv.com; (Ching_Chao@dot.ca.gov); (Douglas_Wright@dot.ca.gov); (mark_woods@dot.ca.gov); (Scott_Kennedy@dot.ca.gov); Aaron Prchlik (aaron_prchlik@dot.ca.gov); Ajay Sehgal (ajay_sehgal@dot.ca.gov); Bernard Feather (Bernard_R_Feather@dot.ca.gov); Bill Shedd (E-mail) (Bill_Shedd@dot.ca.gov); Bob Brignano (bob_brignano@dot.ca.gov); Chandrawinata Martin (Martin_Chandrawinata@dot.ca.gov); Charles Ho (Charles_Ho@dot.ca.gov); Ching Chao (cchao@sasoverseasteam.com); Gil Klebanov (Gilel_Klebanov@dot.ca.gov); Jun Xu (Jun_Xu@dot.ca.gov); Kannu Balan (kannu_balan@dot.ca.gov); Michelle Chui (michelle_chui@dot.ca.gov); Mike Travis (Mike.Travis@LANEngineering.com); Mohammad Awal (mohammad_awal@dot.ca.gov); Ron Matin (ron_matin@dot.ca.gov); Stanley Ku (E-mail) (Stanley_Ku@dot.ca.gov); Tai-Lin Liu (Tai-Lin_Liu@dot.ca.gov); Warren Collins

Subject: ABF-CAL ABF-NPR-000146R2 - ZPMC 158

Please find attached ABF-NPR-000146R2 - ZPMC 158

Kimberly Mackey

American Bridge/Fluor Joint Venture
375 Burma Road Oakland, CA 94607
Direct Line: 510-808-4636 Fax: 510-808-4601
Email: kmackey@abfjv.com

--

This message has been scanned for viruses and dangerous content by [MailScanner](#), and is believed to be clean.

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: xx.25A**QUALITY ASSURANCE -- NON-CONFORMANCE RESOLUTION****Location:** Changxing Island, Shanghai, PRC**Report No:** NCS-000089**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**Date:** 24-Sep-2008**Submitting Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **NCR #:** ZPMC-0158**Type of problem:**

Welding	Concrete	Other	
Welding	Curing	Procedural	Bridge No: 34-0006
Joint fit-up	Coating	Other	Component:
Procedural	Procedural	Descriptor:	

Date the Non-Conformance Report was written: 18-Aug-2008**Description of Non-Conformance:**

ABF allowed ZPMC to weld on the Tower component number NSD1-SA322-B/B-3 & 4 (Double Diaphragm) in the horizontal position with a welder that was not qualified to weld in this position. After the ZPMC Quality Control Inspector was informed of this discrepancy, the welder (Bai Jinhu) was allowed by Mr. Xu Jun to perform welding again in the same position and weld joint. Only after readdressing the issue with the QC Inspector did he stop the welding.

Contractor's proposal to correct the problem:

Upon presentation of ABF/ZPMC's explanation that the welding was being performed in the overhead position the Department concurs that welding was being performed in the overhead (4G) position. Therefore the NCR will be closed with no further action required.

Corrective action taken:

N/A

Did corrective action require Engineer's approval? Yes No**If so, name of Engineer providing approval:****Date:****Is Engineer's approval attached?** Yes No**Comments:**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ryan Smith, (858) 232-6799, who represents the Office of Structural Materials for your project.

Inspected By: Ishibashi, Josh

Quality Assurance Inspector

Reviewed By: Smith, Ryan

QA Reviewer