

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014368**Date Inspected:** 21-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Joe Alaniz was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG Assembly Yard

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as 8AW, 8BW and 8CW X37L, 8BE+8CE hold back welds and 7 East drip plates. The weld designations reviewed are as follows:

7 East Drip Plates

1. OBE7B-001~005

8CE (X37L)

1. CA054-51~54, 63~66

2. SEG048H-11~14

3. SEG048S-57~60

4. SSD24-PP68.5-002

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

5. SSD24-PP69.5-002

8AE

1. CA048-75~78, 87~90
2. SEG044D-11~14
3. SEG044E-57~60
4. SSD23-PP61.5-001
5. SSD24-PP62.5-002

8BE

1. CA051-27~30, 39~42
2. CA051-75~78, 87~90
3. SSD29-PP66.5-001

8BE+8CE

1. SP458-021, 022, 029, 030
2. SP459-021, 022, 029, 030
3. SP579-025, 026
4. SP580-18, 19
5. SP619-025, 026
6. SP620-31, 32
7. SP467-21, 22, 29, 30
8. SP468-11, 12, 19, 20
8. SP317-01, 02
9. SP370-35, 36
10. SP371-11, 12
11. EP086-11, 12
12. EP087-11, 12
13. DP668-15, 16
14. DP669-09, 10
15. DP660-15, 16
16. DP661-09, 10
13. BP176-43, 44
14. BP177-25, 26
15. BP068-43, 44
16. BP069-25, 26
17. BP123-25, 26, 35, 36

7DW+7EW

Shield Metal Arc Welding (SMAW) repair welding was performed on weld joint 008 located at OBW7A deck

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

plate weld splice of segment. Welder is identified as Mr. Zang Yanbo (045196). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-4G (4F)-Repair-1 and CWR1514 repair procedure.

Y Location of repairs areas by above noted welder (045196) is located at 430, 1200 and 1200mm. (Internal)

Shield Metal Arc Welding (SMAW) repair welding was performed on weld joint 006 located at OBW7C counter weight side of segment. Welder is identified as Mr. Zhao Aifei (067942). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-4G (4F)-Repair-1 and CWR1542 repair procedure.

Y Location of repairs areas by above noted welder (067942) is located at 150 and 1160mm. (External)

Shield Metal Arc Welding (SMAW) repair welding was performed on weld joint 006 located at OBW7C counter weight side of segment. Welder is identified as Mr. Xu Changxue (066002). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-4G (4F)-Repair-1 and CWR1542 repair procedure.

Y Location of repairs areas by above noted welder (066002) is located at 630, 1200 and 1590mm. (External)

Shield Metal Arc Welding (SMAW) repair welding was performed on weld joint 008 located at OBW7C cross beam side of segment. Welder is identified as Mr. Zang Yanbo (069683). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-3G (3F)-Repair-1 and CWR1514 repair procedure.

Y Location of repairs areas by above noted welder (069683) is located at 7870mm.

8AW

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 043 located at SEG043A cross beam side of segment. Welder is identified as Mr. Li Zhengqiang (066038). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-P-2214-Tc-U4b-FCM-1.

8BW

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 030 located at SEG047B cross beam side of segment. Welder is identified as Mr. Gong Huaigang (037840). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-T-2214-B-U4b-FCM-1.

8CW

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 001 located at CA050 cross beam side of segment. Welder is identified as Mr. Gong Huaigang (037840). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-T-2214-B-U4b-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 4 of 4)


7DW

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 006 and 043 located at SEG039C cross beam side of segment. Welder is identified as Mr. Tian Zhaoquan (045246). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-345-SMAW-3G (3F)-Repair-1, WR12975 and 12975 procedure.

9AE

Flux Core Arc Welding (FCAW) welding was performed on weld joint 011 located at SEG050A cross beam side of segment. Welder is identified as Mr. Zhang Hanming (220066). ZPMC QC is identified as Li Yang. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-T-2231-B-U2-F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (150-0042-2372), who represents the Office of Structural Materials for your project.

Inspected By:	Alaniz,Joe	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
