

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-017963**Date Inspected:** 21-Oct-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island**Location:** Shanghai, China**CWI Name:** Mr. Xu Tao**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment and Bike Path**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Ultrasonic Testing (UT) – NWIT Document No: 007049

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The members are identified as OBG Steel Barrier. The weld designations reviewed are as follows:

1. W5-SB2-002-019
2. W5-SB1-004-019
3. W5-SB1-023-019
4. W5-SB2-005-081
5. W5-SB1-003-019
6. W5-SB13A-003-019

Ultrasonic Testing (UT) – NWIT Document No: 007053

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The members are identified as OBG Bike Path. The weld designations reviewed are as follows:

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

---

1. BK4SD1-008-022, 023, 024, 027
2. BK4SD1-010-001, 002, 003, 004

OBG Segment 12AE

This QA Inspector observed the following work in progress:

Shielded Metal Arc Welding (SMAW) repair welding of weld joint SEG3001J-002 located on deck plate diaphragm to deck plate diaphragm splice joint of OBG Segment 12AE. Welder is identified as 216086. ZPMC Quality Control (QC) is identified as Mr. Li Ping. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-3G (3F) - Repair, which is used as per Welding Repair Report (WRR) B-WR-16070.

SMAW repair welding of weld joint SEG3001\*-022 located on deck plate to deck plate splice joint of OBG Segment 12AE. Welder is identified as 051359. ZPMC Quality Control (QC) is identified as Mr. Li Ping. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-1G (1F) - Repair, which is used as per Welding Repair Report (WRR) B-WR-16071.

SMAW repair welding of weld joint SEG3001A-009 located on bottom plate to bottom plate splice joint of OBG Segment 12AE. Welder is identified as 054016. ZPMC Quality Control (QC) is identified as Mr. Li Ping. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-1G (1F) - Repair, which is used as per Welding Repair Report (WRR) B-WR-16069.

SMAW repair welding of weld joint SEG3001AL-007 located on side plate to side plate splice joint of OBG Segment 12AE. Welder is identified as 054016. ZPMC Quality Control (QC) is identified as Mr. Li Ping. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-4G (4F) - Repair, which is used as per Welding Repair Report (WRR) B-WR-16068.

SMAW repair welding of weld joint SEG3001AL-009 located on side plate to side plate splice joint of OBG Segment 12AE. Welder is identified as 054016. ZPMC Quality Control (QC) is identified as Mr. Li Ping. The welding variables recorded by QC appeared to comply with the Applicable WPS-345-SMAW-4G (4F) - Repair, which is used as per Welding Repair Report (WRR) B-WR-16118.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

## **Summary of Conversations:**

Only general conversation was held between QA and QC concerning this project.

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

---

---

# WELDING INSPECTION REPORT

*( Continued Page 3 of 3 )*

---

---

<b>Inspected By:</b>	Kumar, Vibin	Quality Assurance Inspector
----------------------	--------------	-----------------------------

<b>Reviewed By:</b>	McClendon, Timothy	QA Reviewer
---------------------	--------------------	-------------