

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 82.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023166**Date Inspected:** 14-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Westmont Industries**Location:** Santa Fe Springs, CA.**CWI Name:** Ruben Dominguez**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Travelers**Summary of Items Observed:**

This Quality Assurance Inspector Sean Vance arrived on site at Westmont Industries (WMI) in Santa Fe Springs, CA, to randomly observe the in process welding, QC inspection, painting and non-destructive testing of the Travelers. Upon the arrival of the QA Inspector, the following observations were made:

Traveler Test Rack

This QA Inspector randomly observed WMI production personnel performing fitting, welding and cutting activities on various assemblies for the Traveler Test Rack.

SAS WB Traveler

This QA Inspector observed WMI production welder Mr. Eutimo Lopez (WID #3035) continuing to perform Flux Core Arc Welding (FCAW) activities on the SAS-WB Traveler frame assemblies. This QA Inspector observed Mr. Lopez performing the FCAW in all positions on tube steel and plate material, randomly throughout the shift.

This QA Inspector observed WMI production welder Mr. Charles Newton (WID #3200) continuing to perform Flux Core Arc Welding (FCAW) activities on the SAS-WB Traveler frame assemblies. This QA Inspector observed Mr. Newton performing the FCAW in all positions on tube steel and plate material, randomly throughout the shift.

Trolley Train Assemblies

This QA Inspector observed WMI production welder Mr. Jose Rodriguez (WID #3031) performing Flux Core Arc Welding (FCAW) activities on the Traveler trolley train assemblies. This QA Inspector observed Mr. Rodriguez

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

performing the activities on plate material, randomly throughout the shift.

This QA Inspector observed WMI production welder Mr. Richard Fuentes (WID #3201) performing Flux Core Arc Welding (FCAW) tacking and fitting activities on the Traveler trolley train assemblies. This QA Inspector observed Mr. Fuentes performing the activities on plate material, randomly throughout the shift.

This QA Inspector observed WMI production welder Mr. Jose Miranda (WID #3083) performing Flux Core Arc Welding (FCAW) tacking and fitting activities on the Traveler trolley train assemblies. This QA Inspector observed Mr. Miranda performing the activities on plate material, randomly throughout the shift.

This QA Inspector randomly observed that Smith Emery QC Inspector Mr. Ruben Dominguez was present, during the above mentioned welding and fitting activities. During random observation, this QA Inspector observed that the applicable WPS's and copies of the shop drawings, appeared to be located near each work station, where the above mentioned welding and fitting activities were being performed. This QA Inspector randomly verified that the consumable material, utilized during the welding appeared to be in compliance with the applicable WPS and that the above mentioned welders were currently qualified for the applicable process and position of welding. This QA Inspector randomly observed QC Inspector Dominguez verifying the in-process welding parameters, including voltage, amperage, pre-heat and travel speed and the parameters appeared to be in compliance to the applicable WPS.

Paint: E2/E3-EB Travelers

This QA Inspector observed that RPI Coating personnel were not present and no sandblasting or painting activities were performed.

This QA Inspector observed that the activities mentioned above, appeared to be in compliance with the contract requirements and this QA Inspector observed no non-conforming issues, on this date.

Summary of Conversations:

As noted above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Vance,Sean	Quality Assurance Inspector
----------------------	------------	-----------------------------

Reviewed By:	Edmondson,Fred	QA Reviewer
---------------------	----------------	-------------