

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
HARDSCRABBLE CRK (VIGGO "VIC" MEED	01-DN-199-11.01	FO	50	None	Rail	Replacement Underway
MIDDLE FORK SMITH RIVER	01-DN-199-24.08	FO	46.8	None	Functional Improvement	
ELK CREEK	01-DN-101-26.15-CRC	SD	50	Culvert	Culvert Repair	
KLAMATH RIVER	01-DN-101-R4.04		50	None	Superstructure	Programmed Repair
KLAMATH RIVER	02-SIS-263-57.07	SD	47	Deck	Deck/Superstructure	Proposed Replacement
LOST RIVER	02-SIS-161-19.18	SD	44.6	Deck	Deck/superstructure	Replacement Underway
RUSH CREEK	02-MOD-299-6.32	SD	4.1	Deck	Deck/Substructure	
EEL RIVER BOH	01-HUM-283-.12	FO	44.2	None	Functional Improvement	
MAD RIVER	01-HUM-101-89.63	SD	49.8	Deck	Deck/Substructure	Programmed Replacement
REDWOOD CREEK	01-HUM-299-R22.33	SD	48	Deck	Deck Joints	Repair Underway
EEL RIVER (FERNBRIDGE)	01-HUM-211-78.1	FO	32	None	Functional Improvement	
WILLOW CREEK	01-HUM-096-.24		49.4	None	Paint	
SHOTGUN CREEK	02-SHA-005-R55.57	SD	39	Super	Superstructure	
LAKE BRITTON	02-SHA-089-29.19	SD	30	Deck	Deck/Superstructure	Proposed Replacement
SACRAMENTO RIVER (ANTLER)	02-SHA-005-R40.16	SD	50	Deck	Deck/Superstructure	Programmed Replacement
WHISKEY CREEK	02-SHA-299-14.17		50	None	Deck Condition	Programmed Repair
DEER CREEK	02-TEH-032-12.91		45.3	None	Low Load Capacity	
NORTH FORK FEATHER RIVER	02-PLU-070-3.07	FO	45.9	None	Functional Improvement	
NORTH FORK FEATHER RIVER	02-PLU-070-5.58	FO	34.5	None	Functional Improvement	
NORTH FORK FEATHER RIVER	02-PLU-070-6.99	FO	49.6	None	Functional Improvement	
SPRING GARDEN BOH	02-PLU-070-51.21	SD	46	Deck	Deck/Rail	Programmed Repair
MC COY CREEK	01-MEN-271-17.88		47.2	None	Low Load Capacity	
JITNEY GULCH	01-MEN-101-93.01	SD	49.8	Deck	Deck Condition	Repair Underway
SALMON CREEK	01-MEN-001-43	SD	49.7	Deck	Deck Joints	Programmed Repair
JUG HANDLE CREEK	01-MEN-001-56.73	SD	33.8	Sub	Substructure	
TEN MILE RIVER	01-MEN-001-69.69	SD	42.1	Super	Superstructure	Replacement Underway
GUALALA RIVER	01-MEN-001-.01	FO	48	None	Functional Improvement	
WILSON GULCH (SUPERCEDED ALIGNME	01-MEN-101-62.69	SD	32	Deck	Deck/Superstructure/Substructure	
LINE CANAL	03-BUT-099-.01	FO	43	None	Functional Improvement	
JUNCTION DRAW	03-BUT-099-13.16	FO	48.2	None	Functional Improvement	
FEATHER RIVER	03-BUT-070-14.83-OV	FO	43.4	None	Superstructure	Programmed Repair
DOWNIE RIVER	03-SIE-049-16.75	FO	38.9	None	Functional Improvement	
BEAR CREEK	03-COL-020-3.28	SD	35	Super	Superstructure	Programmed Replacement
COLFAX OH	03-PLA-174-.62-CFX	SD	49	Deck	Deck Condition	
LONG RAVINE UC	03-PLA-080-34.99	SD	34	Deck	Deck/Superstructure	Proposed Replacement
CAPE HORN UC	03-PLA-080-36.86	SD	50	Deck	Deck/Superstructure	Proposed Replacement
COPELAND CREEK	04-SON-101-13.51-RN	SD	40.4	Str Appr	Inventory Rating	
YELLOW CREEK	04-SON-121-6.52	FO	48.6	None	Functional Improvement	

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
ARROYO SECO	04-SON-121-8.43	FO	50	None	Functional Improvement	Proposed Replacement
LAGUNA DE SANTA ROSA	04-SON-012-9.63	FO	31	None	Substructure	Programmed Replacement
REDWOOD CREEK	04-SON-128-21.76	FO	49.8	None	Functional Improvement	Programmed Replacement
GREEN VALLEY CREEK	04-SON-116-18.66	SD	38.9	Deck	Deck/Superstructure	Proposed Repair
BRANCH ARROYO SECO	04-SON-121-8.51	FO	46.6	None	Rail	Proposed Repair
WINDSOR CREEK	04-SON-101-29.5	SD	43	Culvert	Culvert Repair	
TULUCAY CREEK	04-NAP-121-6.42-NAP	SD	48.1	Str Appr	Inventory Rating	Programmed Replacement
TROUTDALE CREEK	04-NAP-029-47.11	SD	24.4	Str Appr	Inventory Rating	Programmed Replacement
SARCO CREEK	04-NAP-121-9.3	SD	38.6	Str Appr	Inventory Rating	Programmed Replacement
CAPELL CREEK	04-NAP-121-20.29		43	None	Substructure	Programmed Replacement
SODA CREEK	04-NAP-128-18.55	FO	39.8	None	Substructure	Programmed Replacement
WRAGG CREEK	04-NAP-128-27.9	SD	44	Culvert	Culvert Repair	
TAYLOR CREEK	03-YOL-016-20.3	SD	21.6	Str Appr	Inventory Rating	
SACRAMENTO RIVER (KNIGHTS LANDING)	03-YOL-113-22.02	SD	15	Super	Paint/Superstructure	Proposed Repair
N680-E80 CONNECTOR	04-SOL-680-13.14-FR	SD	24.4	Deck	Deck/Superstructure	Proposed Repair
CARQUINEZ LT	04-SOL-080-.01	SD	48.1	Deck	Deck/Substructure	Proposed Repair
WELL CREEK	04-SOL-012-22.91	FO	33	None	Rail	Proposed Repair
SACRAMENTO RIVER (RIO VISTA) BR & S	04-SOL-012-26.24-RV	SD	32	Deck	Deck/Superstructure	Programmed Repair
DRY ARROYO	04-SOL-505-R7.5		47	None	Low Load Capacity	
MINER SLOUGH	04-SOL-084-12.09	FO	33.6	None	Superstructure	Proposed Repair
STEAMBOAT SLOUGH FERRY	04-SOL-220-3.10	SD	39.5	Str Appr	Paint/Superstructure	Proposed Repair
MIDWAY ROAD OC	04-SOL-080-32.62	SD	36	Deck	Deck/ Substructure	Programmed Repair
AMERICAN RIVER	03-SAC-160-R44.47-S	FO	49.9	None	Deck Condition	Programmed Repair
SACRAMENTO RIVER (ISLETON)	03-SAC-160-5.86	SD	11	Deck	Deck/Superstructure	Repair Underway
STEAMBOAT SLOUGH	03-SAC-160-19.76	FO	47.5	None	DeckSubstructure	Proposed Repair
SACRAMENTO RIVER (PAINTERSVILLE)	03-SAC-160-20.87	SD	1	Super	Deck/Superstructure/Substruct	Proposed Repair
THREE MILE SLOUGH	03-SAC-160-6.98	SD	38	Super	Paint/Deck/Superstructure	Proposed Repair
SOUTH CONNECTOR UC	03-SAC-005-22.42-SA	SD	48.5	Deck	Deck Condition	Programmed Repair
ECHO SUMMIT SIDEHILL VIADUCT	03-ED-050-67.3	SD	39	Super	Superstructure	Proposed Replacement
OLEMA CREEK	04-MRN-001-22.96	SD	44.5	Deck	Deck/Substructure	Proposed Repair
LAGUNITAS CREEK	04-MRN-001-28.51	SD	35.8	Super	Rail/Superstructure	Proposed Repair
ESTERO AMERICANO	04-MRN-001-50.47	SD	41.4	Deck	Deck/Substructure	Proposed Replacement
HILLTOP DRIVE OC	04-CC-080-5.98-RCH	SD	47	Deck	Deck/Superstructure	Programmed Replacement
STANISLAUS RIVER	10-SJ-099-0	SD	14	Deck	Deck/Superstructure	Proposed Replacement
W120-S5 CONNECTOR	10-SJ-120-T.11	SD	13.1	Deck	Deck/Superstructure	
MOKELUMNE RIVER	10-SJ-012-.01	FO	44.9	None	Deck/Superstructure	Repair Underway
OLD RIVER	10-SJ-004-.01	FO	45.1	None	Paint/Rail	Proposed Repair
MIDDLE RIVER	10-SJ-004-4.42	SD	42.6	Deck	Deck/Substructure	Programmed Repair

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
SAN JOAQUIN RIVER (GARWOODS)	10-SJ-004-14.15	SD	36	Deck	Rail/Deck/Superstructure	Proposed Repair
E26-N99 CONNECTOR OC	10-SJ-026-1.08-STKN	SD	47	Super	Superstructure	
HANSEN ROAD OC	10-SJ-205-2.38	SD	49.4	Super	Paint/Superstructure	Proposed Repair
SOUTH FORK STANISLAUS RIVER	10-TUO-108-31.24	FO	43.6	None	Rail	Proposed Repair
UNIVERSITY AVENUE OC	04-ALA-080-5.82-BER	FO	50	None	Deck Condition	Programmed Repair
SFOBB EAST BAY	04-ALA-080-1.15-OAK	SD	15.1	Super	Paint/Superstructure	Replacement Underway
FIFTH AVENUE OVERHEAD	04-ALA-880-30.38-OA	SD	47	Deck	Paint/Deck/Superstructure	Programmed Replacement
HIGH STREET SEPARATION & OH	04-ALA-880-27.63-OA	SD	26	Deck	Paint/Deck/Superstructure	Programmed Replacement
HIGH STREET SEPARATION & OH	04-ALA-880-27.63-OA	SD	32	Deck	Paint/Deck/Superstructure	Programmed Replacement
W80-S13 CONNECTOR OC	04-ALA-080-4.45-EMV	SD	45	Deck	Rail/Deck/Superstructure	Programmed Repair
SFOBB WEST BAY	04-SF-080-6.35-SF	FO	49.3	Deck	Deck/Superstructure	Proposed Repair
MARINA VIADUCT	04-SF-101-8.33-SF	SD	24.8	Deck	Deck/Superstructure	Proposed Replacement
WEST PACIFIC AVENUE UC	04-SF-001-6.18-SF	SD	47	Deck	Deck Condition	Programmed Repair
RUCKMAN AVENUE UC	04-SF-001-6.86-SF	SD	31.3	Deck	Deck/Superstructure	Proposed Repair
PRESIDIO VIADUCT	04-SF-101-9.14-SF	SD	2	Deck	Paint/Deck/Superstructure	Proposed Replacement
BAYSHORE VIADUCT	04-SF-101-4.12-SF	SD	49	Deck	Deck Condition	Programmed Repair
SFOBB-APPROACH-UPPER DECK	04-SF-080-4.95-SF	FO	29	None	Substructure	Replacement Underway
SFOBB-APPROACH LOWER DECK	04-SF-080-4.95-SF	FO	49	None	Substructure	Replacement Underway
COLMA CREEK	04-SM-082-22.36-CLM		46	None	Rail	Proposed Repair
WEST UNION CREEK	04-SM-084-19.89-WDS	SD	28	Str Appr	Rail	Proposed Repair
PENINSULA AVENUE OC	04-SM-101-14.69-SM	SD	47	Deck	Deck Condition	Programmed Replacement
BOULDER CREEK	05-SCR-236-2.86	FO	39	None	Rail	Proposed Repair
BOULDER CREEK	05-SCR-236-1.61	FO	39	None	Rail	Proposed Repair
BOULDER CREEK	05-SCR-236-1.03	FO	39	None	Rail	Proposed Repair
SCOTT CREEK	05-SCR-001-31.55	SD	48.1	Deck	Deck Condition	Programmed Replacement
SAN LORENZO RIVER	05-SCR-009-7.76	FO	47.4	None	Rail	Proposed Repair
WADDELL CREEK	05-SCR-001-36.3	SD	48.7	Deck	Deck Condition	Programmed Replacement
SARGENT BRIDGE & OH	04-SCL-101-R.81	SD	32	Deck	Rail/Deck/Superstructure	Programmed Repair
SARATOGA CREEK	04-SCL-009-4.85	FO	29.1	None	Superstructure	Proposed Replacement
TULLY ROAD OC	04-SCL-101-33.03-SJS	SD	45	Deck	Deck/Superstructure	Programmed Repair
HESTER PUC	04-SCL-082-9-SJS		45	None	Low Load Capacity	
YOSEMITE DRIVE OC	04-SCL-680-M6.98-MF	FO	50	None	Functional Improvement	
CALAVERAS BOULEVARD OH	04-SCL-237-10.2-MPS	SD	48.2	Deck	Deck Condition	Programmed repair
BRANCH BLACK RASCAL CANAL	10-MER-059-16.01	FO	49.5	None	Rail	Programmed Repair
FRANKLIN ROAD OC	10-MER-099-18.51	SD	49.4	Super	Superstructure	
APPLEGATE ROAD OC	10-MER-099-22.76-AT	SD	48.6	Super	Superstructure	
WEST MERCED OVERHEAD	10-MER-099-16.54	SD	38.2	Super	Paint/Superstructure	Proposed Repair
WEST MERCED OVERHEAD	10-MER-099-16.54	SD	45.9	Super	Paint/Superstructure	Proposed Repair

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
SAN JOAQUIN RIVER	10-MER-165-25.61	SD	45.7	Sub	Substructure	Programmed Replacement
EAST SIDE CANAL	10-MER-165-28.14	SD	48.2	Culvert	Culvert Repair	Proposed Repair
BEAR CREEK	10-MPA-140-34.08	FO	50	None	Rail	Proposed Repair
SLATE GULCH	10-MPA-140-37.09	FO	39	None	Functional Improvement	
WARTHAN CREEK	06-FRE-198-1.82	FO	45.6	None	Functional Improvement	
FRESNO SLOUGH (KINGS RIVER - WHITE)	06-FRE-180-26.95	SD	39	Sub	Substructure	Proposed Repair
KINGS RIVER OVERFLOW	06-FRE-180-77.19	SD	31.2	Deck	Deck/Superstructure	Proposed Replacement
CANTUA CREEK	06-FRE-005-28.5	SD	36	Deck	Deck/Superstructure	Repair Completed
CANTUA CREEK	06-FRE-005-28.5	SD	36	Deck	Deck/Superstructure	Repair Completed
THREE ROCKS ROAD UC	06-FRE-005-35.26	SD	36	Deck	Deck/Superstructure	Repair Completed
THREE ROCKS ROAD UC	06-FRE-005-35.26	SD	36	Deck	Deck/Superstructure	Repair Completed
FIVE POINTS UC	06-FRE-005-15.96	SD	36	Deck	Deck/Superstructure	Repair Completed
FIVE POINTS UC	06-FRE-005-15.96	SD	36	Deck	Deck/Superstructure	Repair Completed
DOMENGINE UC	06-FRE-005-22.85	SD	36	Deck	Deck/Superstructure	Repair Completed
DOMENGINE UC	06-FRE-005-22.85	SD	36	Deck	Deck/Superstructure	Repair Completed
PARKHURST EQUIPMENT UC	06-FRE-005-26.8	SD	36	Deck	Deck/Superstructure	Repair Completed
PARKHURST EQUIPMENT UC	06-FRE-005-26.8	SD	36	Deck	Deck/Superstructure	Repair Completed
GRANITE CANYON	05-MON-001-64.33	FO	48.8	None	Rail	Proposed Repair
BIXBY CREEK	05-MON-001-59.37	FO	50	None	Rail	Proposed Repair
CASTRO CANYON	05-MON-001-43.12	FO	47.2	None	Deck/Rail	Proposed Repair
ROCKY CREEK	05-MON-001-60.05	FO	46.3	None	Deck/Rail	Proposed Repair
BIG CREEK	05-MON-001-28.09	FO	50	None	Rail	Proposed Repair
MILL CREEK	05-MON-001-18.46	FO	49.2	None	Rail	Proposed Repair
W LAUREL DRIVE OC	05-MON-101-R89.27	SD	50	Deck	Deck Condition	Proposed Repair
SOUTH PORTERVILLE OH	06-TUL-190-16.45-PTF	SD	37.5	Super	Superstructure	Repair Underway
YOKOHL CREEK	06-TUL-198-21.82	SD	47.6	Deck	Deck/Superstructure	Proposed Repair
SALT CREEK	06-TUL-198-41.23	FO	46	None	Rail	Proposed Repair
KAWEAH RIVER	06-TUL-198-43.92	SD	31.8	Super	Superstructure	Proposed Repair
N99-K STREET OFF-RAMP OC	06-TUL-099-26.05	SD	28	Deck	Deck Condition	Replacement Completed
NORTH PASO ROBLES OH	05-SLO-101-58.76-PS	SD	21.3	Deck	Deck/Superstructure	Proposed Repair
NORTH PASO ROBLES OH	05-SLO-101-58.76-PS	SD	34	Deck	Deck/Superstructure	Proposed Repair
SOUTH PASO ROBLES OH	05-SLO-101-55.72	SD	34	Super	Superstructure	Repair Underway
SOUTH PASO ROBLES OH	05-SLO-101-55.67	SD	35	Super	Superstructure	Repair Underway
GOOSE LAKE CANAL	06-KER-046-35.13	SD	41	Sub	RailSubstructure	Proposed Repair
KERN RIVER	06-KER-204-5.61	SD	48.1	Deck	Deck/Substructure	Proposed Repair
CANE BRAKE CREEK	06-KER-178-76.98		48.6	None	Low Load Capacity	
SIDEHILL VIADUCT NO. 1	06-KER-178-13.74	FO	47.4	None	Rail	Proposed Repair
SIDEHILL VIADUCT NO. 2	06-KER-178-13.76	FO	49	None	Rail	Proposed Repair

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
SIDEHILL VIADUCT NO. 3	06-KER-178-13.78	FO	40.6	None	Rail	Proposed Repair
ARROYO PARIDA	05-SB-101-R5.63	SD	33.6	Deck	Deck/Substructure	Proposed Replacement
MISSION CREEK	05-SB-192-3.36	FO	40.9	None	Rail	Proposed Repair
MONTECITO CREEK	05-SB-192-8.12	FO	42.7	None	Rail	Proposed Repair
ARROYO PARIDA	05-SB-192-15.52	SD	32.6	Str Appr	Substructure	Programmed Replacement
HOLLISTER AVENUE OC	05-SB-101-26.91	SD	39.8	Deck	Deck/Substructure	Programmed Replacement
RINCON CREEK	05-SB-150-2.19	FO	27.8	None	Rail	Proposed Repair
LION CANYON CREEK	07-VEN-150-23.93	FO	34.5	None	Functional Improvement	
CANON CREEK	07-VEN-033-20.48		49.1	None	Rail	Proposed Repair
MAIN STREET OC	07-LA-001-35.07-SMC	SD	45.3	Str Appr	Rail	Proposed Repair
GARAPITO CREEK	07-LA-027-6.56	SD	46.5	Str Appr	Inventory Rating	
SANTA CLARA RIVER	07-LA-005-R53.70-SC	SD	40.5	Deck	Deck/Substructure	Replacement Completed
LACTC ACCESS ROAD OC	07-LA-710-10.31-LBCH	SD	37	Str Appr	Inventory Rating	
HOBART YARD OH	07-LA-710-22.17-VER	FO	50	None	Functional Improvement	Widen
EAST YARD OH	07-LA-710-22.66-CMR	SD	48	Deck	Deck Condition	Programmed Repair
CLEVELAND STREET PUC	07-LA-010-44.7-POM	FO	48	None	Functional Improvement	
MOUNTAIN AVENUE PUC	07-LA-010-47.24-CLA	FO	43	None	Functional Improvement	
EB 60/5 SEPARATION	07-LA-060-R.63-LA	SD	49	Deck	Paint/Deck/Superstructure	Proposed Repair
TEXACO OH	07-LA-001-8.69-LA	SD	22	Sub	Substructure	Proposed Repair
CEDAR VALLEY WAY OC	07-LA-014-R30.55	SD	38.8	Str Appr	Inventory Rating	
SCHUYLER HEIM LIFT BRIDGE	07-LA-047-3.58-LBCH	SD	27.9	Super	Deck/Superstructure/Substruct	Programmed Replacement
ROUTE 10,5/101 SEPARATION	07-LA-005-16.9-LA	SD	21	Super	Superstructure	Programmed Repair
SANTA MONICA VIADUCT "C"	07-LA-010-14.88-LA	SD	45	Deck	Deck Condition	Proposed Repair
SANTA MONICA VIADUCT "F"	07-LA-010-17.54-LA	SD	46	Deck	Deck Condition	Proposed Repair
BIG BEAR LAKE DAM BRIDGE	08-SBD-018-44.33	SD	37.7	Deck	Deck/Superstructure/Substruct	Programmed Replacement
EAST FORK CITY CREEK	08-SBD-330-33.68	FO	49.1	None	Rail	Programmed Repair
WASHINGTON AVENUE OC	08-SBD-215-2.69-COL	SD	20.2	Deck	Deck/Superstructure	Proposed Repair
MARBLE WASH	08-SBD-040-R80.42	SD	38.1	Super	Superstructure	Replacement Completed
MARBLE WASH	08-SBD-040-R80.44	SD	39.1	Super	Superstructure	Replacement Completed
FORTRESS WASH	08-SBD-040-R90.53	SD	39.1	Super	Superstructure	Replacement Completed
FORTRESS WASH	08-SBD-040-R90.52	SD	39.1	Super	Superstructure	Replacement Completed
NEPRUD WASH	08-SBD-040-R91.64	SD	39.1	Super	Superstructure	Replacement Completed
NEPRUD WASH	08-SBD-040-R91.66	SD	39.1	Super	Superstructure	Replacement Completed
MACDONALD WASH	08-SBD-040-R94.37	SD	39.1	Super	Superstructure	Replacement Completed
MACDONALD WASH	08-SBD-040-R94.37	SD	39.1	Super	Superstructure	Replacement Completed
CHUCKWALLA WASH	08-SBD-040-R97.14	SD	39.1	Super	Superstructure	Replacement Completed
CHUCKWALLA WASH	08-SBD-040-R97.14	SD	39.1	Super	Superstructure	Replacement Completed
MUSTANG WASH	08-SBD-040-R97.62	SD	39.1	Super	Superstructure	Replacement Completed

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating

Priority Structurally Deficient Bridge List and Sufficiency Rating 50 or Less

Structure Name	Location	SD* or FO**	SR***	SD Control	Description of Need	Project Status
MUSTANG WASH	08-SBD-040-R97.62	SD	35.9	Deck	Deck/Superstructure	Replacement Completed
COLORADO RIVER	08-SBD-062-142.6	SD	6	Sub	Substructure	Programmed Repair
SAN JUAN CANYON	12-ORA-074-13.29-SJ	SD	24.8	Str Appr	Rail	Proposed Repair
STRAWBERRY CREEK	08-RIV-074-53.45	FO	49.5	None	Rail	Proposed Repair
AGUA HEDIONDA LAGOON	11-SD-005-R48.68-CB	SD	38	Deck	Deck/Substructure	Proposed Repair

8/9/2007

- * - Structurally Deficient
- ** - Functionally Obsolete
- *** - Sufficiency Rating