

## Appendix H Project Photographs (Existing and Proposed)

---

### Photos of Existing Conditions



**Photo 1. Rockwall Sidehill 1, view southeast (DSCN1872).**



**Photo 2. Rockwall Sidehill 2, view southeast (DSCN1873).**



**Photo 3. Johnson Pass Sidehill, view southwest (DSCN1875).**



**Photo 4. Johnson Pass Sidehill, view south (DSCN1877).**



**Photo 5. Johnson Pass Sidehill, view north (DSCN1878).**



**Photo 6. Midway Sidehill, view southeast (DSCN1879).**



**Photo 7. Midway Sidehill, view south (DSCN1880).**



**Photo 8. Meyers Grade Sidehill, north end, view south (DSCN1883).**



**Photo 9. Meyers Grade Sidehill, damage at south end, view southeast (DSCN1885).**




**Photo 10. Lauren's Lookout Sidehill, view southeast (DSCN1886).**



**Photo 11. Lauren's Lookout Sidehill, view south (DSCN1887).**



**Photo 12. Lauren's Lookout Sidehill, damage at midpoint, view northeast (DSCN1888).**



**Photo 13. Robbin's Run Sidehill, view south (DSCN1890).**



**Photo 14. Robbin's Run Sidehill, view southeast (DSCN1891).**

## Photo Simulation of Proposed Wall Barrier



Echo Summit - Photo simulation of the proposed wall barrier - viewing it from the highway.



Echo Summit - Photo simulation of the proposed wall barrier - viewing the outside of the wall.