




Existing Conditions



Proposed Conditions

*figure 6:* Aerial view at site of proposed quarry undercrossing and stormwater detention basin.