



Photograph No. 1
PCC Grinder and Containment Truck (Typical)




Photograph No. 2
PCC Grinding Operation (Typical)



Photograph No. 3
Inlet / Outlet Hoses (Typical)



Photograph No. 4
Tanker Discharge Pipes (Typical)



Photograph No. 5
Tanker Hatch Covers (Typical)



Photograph No. 6
PCC Solid Waste in Discharge Pipe (Typical)



Photograph No. 7
PCC Waste Discharge at Off-site Disposal Facility Open Lined Pit (Typical)



Photograph No. 8
Off-site Disposal Facility Open Lined Pit (October 26, 2004)



Photograph No. 9
Slurry / Solids Sampling (Typical)



Photograph No. 10
Grinding Steam (Typical)



Photograph No. 11
Grinding Thickness (Typical)
(Note marker width = 0.7")



Photograph No. 12
Cemex Facility 1 (January 19, 2005)



Photograph No. 13
Cemex Facility 2 (January 19, 2005)



Photograph No. 14
Cemex Facility 3 (January 19, 2005)