



EA	04-0120F4
Co-Rte-KP (PM)	SF-080-13.2/13.9 (8.2/8.7)
Structure Rep.	Rick Morrow




File Name:	DSC00372
Date:	12-13-07

By Int: SH Song
 Description: The torque wrench was set to 400 lb-ft per HRC's recommendation, and submittal 293R1.

File Name:	DSC00375
Date:	12-13-07

By Int: SH Song
 Description: Mechanical couplers that were torqued to the specified 400 lb-ft were spray painted orange. Approximately 90+ couplers were completed today.



File Name:	DSC00379
Date:	12-13-07

By Int: SH Song
 Description: Pamela and Song watched Tim and Jorge torque each mechanical coupler to 400 lb-ft. A "clicking" noise is heard when the coupler obtain the specified torque.

File Name:	DSC00382
Date:	12-13-07

By Int: SH Song
 Description: B4 layer reinforcing 2x2-43HBT04* to be placed in the Northeast corner of W2 cap beam. 2x20-43B4T07* bars are seen in the back corner.