

EA	04-0120F4
Co-Rte-KP (PM)	SF-080-13.2/13.9 (8.2/8.7)
Structure Rep.	Rick Morrow



File Name:	May-06-2009 W2 Cap 005
------------	------------------------

Date:	05-06-09	By Int:	M Bruce
-------	----------	---------	---------

Description: Dust being blown out of continuity tendon W-4B. There was minimal water coming out of the ducts and mostly dust when running the rabbit. The only ducts that were obstructed were E-10B and E-11B where concrete was found in the ducts prior.

File Name:	May-06-2009 W2 Cap 006
------------	------------------------

Date:	05-06-09	By Int:	M Bruce
-------	----------	---------	---------

Description: SDI ironworkers running the rabbit and ABF piledrivers placing double channel supports under the falsework cap beams from the manlift.