

**JOB STAMP**  
 04-0120F4  
 04-SF-80-12.6/13.2  
 San Francisco Oakland Bay Bridge  
 Self Anchored Suspension Span

REPORT NO.	886	to	892	DATE	May 17 – May 23, 2009	S T W Th F S
SHIFT HOUR	START	Var.	STOP	Var.	TEMPERATURE	
WEATHER	Sunday	Monday –	Tuesday –	Wednesday –	Thursday –	Friday -Saturday –

**17 May**

No Work on Site

**18 May**

1. Reviewed email and PMIV Correspondence.
2. Finalized Diary for week 10-May-2009.
3. **Sub 1087:** Emailed Nhan (TY-Lin) regarding questions I had on the locations of several scribe lines depicting stiffeners and also had questions about bolt holes being shown inconsistent to Contract Plans. Nhan is aware and awaiting his response on these issues.
4. **Sub 383R04:** Verified that the bolt spacing of 85mm for the splice plates near the top of Shear Plates are consistent with RFI 405R0. The weld details shown have been submitted for review. Rathole along the Segment Splice is consistent with RFI 1676R0.

**19 May**

1. Reviewed email and PMIV Correspondence.
2. Continued to review Submittal 383R04 and verified additional RFI comments were incorporated.
3. Reviewed Submittal 1088.

**20 May**

1. Reviewed email and PMIV Correspondence.
2. Generated a Draft Letter for an update to Submittal 202R8. It is not possible to increase the railing heights as originally planned due to the electrical service platform being directly under the smaller platform resulting in insufficient clearance.
3. Reviewed Completeness for Submittal 409R02, 354R02 and 411R05.

**21 May**


1. Reviewed email and PMIV Correspondence.
2. Attended a one (1) hour Safety Meeting.
3. Reviewed TY-Lin's comments and generated draft State Letter's for Submittal's 383R04, 1082R01, 1081R02 and 1081R01.
4. Submittal 1088: Began verifying if referenced callouts have been submitted for review.

**22 May**

1. Reviewed email and PMIV Correspondence.
2. **Submittal 1088:**
  - Verified all referenced callouts
  - Per Contract Plans 712/1204, bulkhead shown in Sheet SA3325 is SPCM. Weld details are consistent with plate size.
  - Callout "X4687G" should be revised to read "X4697G." Will send an email to TY-Lin on this revision once I've completed my review.
3. Created draft State Letter's for Submittal 409R02 and 354R02.
4. Worked on Diary for this week.

**23 May**

No Work on Site

Victor Altamirano SIGNATURE 	29-May-09	TITLE
Senior SIGNATURE 	JAN 13 2010	Transportation Engineer / Assistant Struct. Rep.

REP: HC2 JAN21 #011849

46-02