

JOB STAMP

04-0120F4  
 04-SF-80-12.6/13.2  
 San Francisco Oakland Bay Bridge  
 Self Anchored Suspension Span

REPORT NO.	928	to	934	DATE	June 28 – July 4, 2009	S T W Th F S
SHIFT HOUR	START	Var.	STOP	Var.	TEMPERATURE	
WEATHER	Sunday	Monday –	Tuesday –	Wednesday –	Thursday –	Friday -Saturday –

**28 June**

No Work on Site

**29 June**

1. Reviewed email and PMIV Correspondence.
2. Submittal's 224R08, R09, 491R07 were assigned to other staff members at G. Lai's request in order to send attachments back to ABF. Submittal 1088 was re-assigned to another staff also at G. Lai's request.
3. Finalized last weeks Diary.
4. Attended DJV meeting.
5. Created Drafts for State Letters for Submittal's 202R9, 556R7 & 1109R0. Made additional comments to the draft for submittal 1161. Awaiting response from Nhan (DJV) regarding questions I have on Submittal 1109.

**30 June**

1. Reviewed email and PMIV Correspondence.
2. Attended DJV meeting.
3. **S1109:** The questions were answered from DJV and based on their response, no updated shop drawings are required (see attachments). At a late notice, this submittal will now require a CRM at the Contractor's request.

**1 July**

1. Reviewed email and PMIV Correspondence.
2. Reviewed and revised draft letter for Submittal's 1128 and 1129 for Martin Chandrawinata (CT).
3. No 9am DJV meeting today.

**2 July**

1. Reviewed email and PMIV Correspondence.
2. Attended a 1 hour safety meeting.
3. Reviewed Sub 1128 to verify if the Cable Tray Supports are leveled relative to each other.


**3 July**

Took an 8 hour furlough today.

**4 July**

No Work on Site

RECT#02 FEB-03 #011861

Victor Altamirano SIGNATURE 	TITLE
Senior SIGNATURE	Transportation Engineer / Assistant Struct. Rep.

JAN 16 5 09 PM '09  
 JAN 13 2010





> Nhan,  
>  
>  
>  
>  
> Sheet  
> CB3003C:  
>  
> 1.  
> The plates shown for the traveler rail on the Bottom  
> Plate - Plan View  
> should be re-detailed to show 4 bolt holes, not 2.  
> Refer to detail view E  
> thru H. Please confirm.  
>  
> 2.  
> On detail view E thru H, should the bolts be aligned  
> with the adjacent  
> bolt holes? Refer to Contract Plan Sheet 956, Typical  
> Support. This  
> was redlined in submittal 509R0, sheet CB203C, however  
> wasn't reflected in the  
> latest sheet in Sub 838R01. Please  
> confirm.  
>  
>  
>  
> Thank  
> you.  
>  
>  
> Victor  
> Altamirano  
>  
> 333 Burma Road  
>  
> Oakland , Ca  
> 94607  
>  
> (510)-286-0496 (office)  
>  
> (510)-867-6155 (cell)  
>  
>  
>  
>  
>  
>  
>  
>