

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010931**Date Inspected:** 01-Jan-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, M. Manikandan was present during the time noted above for observations relative to the work being performed.

**OBG # TRIAL ASSEMBLY YARD**

This QA inspector performed U-Rib dimensional survey for below segment. Reports forwarded to team leader for further action

6AW-6BW

This QA Inspector randomly observed the following work in progress:

**OBG # TRIAL ASSEMBLY YARD (6BW-6CW)**

ZPMC performed Heat straightening on T-Rib of side panel SP754+SP516A +SP476 located on 6CW facing 6BW segment. ZPMC CWI is identified as Li Yang. Heat straightening was performed against Caltrans approved report and appeared to comply with the HSR (B)-342.

**OBG # TRIAL ASSEMBLY YARD (6AE-6BE)**

ZPMC performed flame cutting and removed welds of 6AE and 6BE transverse splice weld located on side panel

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

crossbeam side. ZPMC CWI is identified as Li Yang. Cutting was been performed against welding repair report B-WR9154 Rev.0.

OBG # TRIAL ASSEMBLY YARD (6AW)

SMAW Process:

Welding of weld joint – 003 located on PCMK OBW6F, Counter weight connection plate. Welder is identified as 037743. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-Tc-U4b-FCM-1.

OBG # TRIAL ASSEMBLY YARD (6AW-6BW)

SMAW Process:

Welding of weld joint – 004 located on PCMK SEG029A, Longitudinal weld joining side and bottom panel. Welder is identified as 037743. ZPMC CWI is identified as Li Yang. Welding was been performed against welding repair report B-WR8922 Rev.0. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

SMAW Process:

Welding of weld joint – 004 located on PCMK SEG029A, Longitudinal weld joining side and bottom panel. Welder is identified as 066674. ZPMC CWI is identified as Li Yang. Welding was been performed against welding repair report B-WR8922 Rev.0. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

**Summary of Conversations:**

No Relevant Conversation.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Manikandan,Murugan	Quality Assurance Inspector
----------------------	--------------------	-----------------------------

---

<b>Reviewed By:</b>	Miller,Mark	QA Reviewer
---------------------	-------------	-------------