

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-012185**Date Inspected:** 18-Feb-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Xi.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Bay 1:

This QA Inspector observed the following work in progress:

Flux Cored Arc Welding (FCAW) of OBG component - Traveler Rail, weld joint 20TR1-020 – 005 & 007.

Welder is identified as 219188. ZPMC Quality Control (QC) is identified as Yin Dong Hai. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-T-2231-TC-U5-7-1G.

For Cross Beams (CB):

Bay6: CB9.

This QA Inspector observed that no significant work was being performed on this CB at the time when this QA was present.

Outside Yard:

CB8, CB13, CB10, CB11, CB16, CB12 & CB14:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed that no significant work was being performed on the above mentioned CB's at the time when this QA was present.

CB15:

During random inprocess visual inspection of this Cross Beam, this QA Inspector observed the following observations:

- Some of the welds having poor weld profile and slag not removed.
- Some of the cope holes do not appear to comply with the contract documents.

This QA Inspector has marked above mentioned such locations in question for the Contractors QC to inspect and evaluate. Fabrication of this CB is in progress and is not yet released for Caltrans inspection.

No other significant work was being performed on the above mentioned CB at the time when this QA was present.


Attached are the photos for further information.

Trial Assembly: CB6.

This QA Inspector observed the following work in progress:

Shielded Metal Arc Welding (SMAW) of hold back joints of Bottom panel (BP201A) to Intermediate Diaphragm (FB202E), weld joint nos: CB202A-006 - 010, 023, 012 & 024. Welder is identified as 066261. ZPMC Quality Control (QC) is identified as Li Yang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-B-P-2212-TC-U4B-FCM-1G.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar,Sailesh	Quality Assurance Inspector
----------------------	----------------	-----------------------------

Reviewed By:	Hall,Steven	QA Reviewer
---------------------	-------------	-------------