

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015067**Date Inspected:** 23-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Joe Alaniz was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG Assembly Yard

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member(s) is/are identified as 8CW+8BW T stiffeners and I Ribs hold back welds. The weld designations reviewed are as follows:

8CW+8BW

1. SP103-41, 42
2. SP103-31, 32
3. SP129-25, 26
4. SP130-06, 05
5. SP157-25, 26
6. SP435-21, 22
7. SP446-23, 24
8. SP487-29, 30
9. SP487-41, 42

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

10. SP762-28, 29
11. SP727-53, 54
12. SP725-11, 12
13. SP766-41, 42
14. SP767-43, 44
15. SP489-62, 63
16. SP489-54, 55
17. EP063-11, 12
18. EP064-11, 12
19. EP075-09, 10
20. EP074-10, 09
21. BP041-43, 44
22. BP041-53, 54
23. BP094-65, 66
24. BP095-45, 46
25. BP148-63, 64
26. BP149-51, 52
27. DP653-17, 18
28. DP645-14, 13
29. DP644-17, 18
30. DP652-08, 07

9BE+9CE

Flux Core Arc Welding (FCAW) welding was performed on weld joint 009 located at OBE9 deck plate splice cross beam side of segment. Welder is identified as Mr. Zhou Pan (220063). ZPMC QC is identified as Wu Zhi Cheng. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-T-223(2)1T-2.

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 021 located at DP071-001 cross beam side of segment. Welder is identified as Mr. Li Yongshui (067656). ZPMC QC is identified as Wu Zhi Cheng. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-T-3213-B-U3b.

Shield Metal Arc Welding (SMAW) welding was performed on weld joint 044 located at SEG052A-001 cross beam side of segment. Welder is identified as Mr. Luo Xuanping (068764). ZPMC QC is identified as Wu Zhi Cheng. The welding variables monitored and recorded by the QC appeared to comply with WPS-B-P-2214-Tc-U4b-F-1.

Miscellaneous Work In Progress

QA Inspector observed ZPMC's personnel performing various job functions at Tail Assembly Yard. Locations and description of work are as followed:

8 East and 8 West

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

1. Sea fasteners and cable trays are being installed at various locations inside segment.

7 West

1. Coating (final) in progress at various locations (internal/ external) on segment.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (150-0042-2372), who represents the Office of Structural Materials for your project.

Inspected By:	Alaniz,Joe	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
