

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-017987**Date Inspected:** 09-Nov-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Mr. M. Manikandan was present during the time noted above for observations relative to the work being performed.

**OBG # OUTSIDE YARD (12AW)**

This QA inspector along with QA inspector Mr. Manjunath S Math performed dimensional joint survey inspection on the floor beam to verify the flatness using 1500mm straight edge. The measurements were recorded on a separate sheet and forwarded to team leader for review and disposition. The segment and panel point designations were as follows:

Segment 12AW – PP 109, 110, 111 and 112

**OBG # OUTSIDE YARD (12AW)**

This QA inspector along with QA inspector Mr. Manjunath S Math performed dimensional joint survey inspection on the corner assembly cope hole to verify the radius using 150mm rule. The measurements were recorded on a separate sheet and forwarded to team leader for review and disposition. The segment and panel point designations were as follows:

Segment 12AW – PP 109, 109.5, 110, 110.5, 111, 11.5, 112 and 112.5

---

---

# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

## OBG # OUTSIDE YARD (12AW)

This QA inspector along with QA inspector Mr.Manjunath S Math performed dimensional joint survey inspection on the deck panel to deck panel diaphragm to verify the plumbness and flatness using right angle and 710mm rule. The measurements were recorded on a separate sheet and forwarded to team leader for review and disposition. The segment and panel point designations were as follows:

Segment 12AW – PP 109, 109.5, 110, 110.5, 111, 11.5, 112 and 112.5

## OBG # OUTSIDE YARD (12BE)

This QA inspector along with QA inspector Mr.Manjunath S Math performed the dimensional survey inspection after heat straightening on the deck panel diaphragm to verify the flatness and plumbness on segment 12BE. The measurements were recorded on a separate sheet and forwarded to team leader for review and disposition. The segment and panel point designations were as follows:

Segment 12BE – PP 113

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### **Summary of Conversations:**

No relevant conversations were reported on this date.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Manikandan,Murugan	Quality Assurance Inspector
----------------------	--------------------	-----------------------------

---

<b>Reviewed By:</b>	Peterson,Art	QA Reviewer
---------------------	--------------	-------------