

NON-CQNFORMANCE REPORT	NCR Number 18
-------------------------------	--------------------------

Location of Mat'/Item: 10E1B1
Title/Description :
Group: Foundation
Superintendent: Terry Dupras
Foreman: Rich Semon

Reeort of Condition/Cause of Non-Conformance:
Small amount of rain water ran down the weld zone. There was approximetly 4" of weld in the root at 1B1.

Recommended Corrective Action:
Remove weld by carbon arcing. Clean weld zone, MT, and reweld.

Originator Signature: <i>Nancy J. Evans</i>	Date: 11/17/03	Superintendent Signature: <i>Terry A. Dupras</i>	Date: 11/17/03
---	--------------------------	--	--------------------------

Designer Comments on Corrective Action:

Corrective Actions Verified Complete and Inspected:

Reference Documents:

Date Closed:	
Superintendent Signature:	