

NON-CONFORMANCE REPORT

29

Location of Mat'/Item: E6E SLEEVE 3 PLATE H WELD 2

Title/Description:

Group: FOUNDATION

Superintendent: JIM GILL

Foreman: ANGEL LEON

Report of Condition/Cause of Non-Conformance:

WELDER PUT IN 4 FCAW-G PASSES OVER UNTESTED ROOT PASS AT 3H2.

Recommended Corrective Action:

WELD 3H2 WAS MAGNETIC PARTICLE TESTED USING A DC CURRENT YOKE AND NO INDICATIONS WERE FOUND.

THE WELDER AND FOREMAN EACH RECEIVED WRITTEN VERBAL WARNINGS.



RECOMMEND ACCEPT AS IS.

Originator Signature:

Date: 2/23/04

Superintendent Signature:

Date: 2/23/04



2/23/04

Designer Comments on Corrective Action:

Corrective Actions Verified Complete and Inspected:

Reference Documents:

Date Closed:

Signature: