

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002665**Date Inspected:** 26-May-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 630**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Fu Yu Hong**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower and OBG**Summary of Items Observed:**

CALTRANS Quality Assurance (QA) Inspector, Alfredo Acuna was present for the fabrication scheduled for this project at the ZPMC facility in Shanghai, China for the San Francisco Oakland Bay Self Anchored Suspension Bridge.

**Tower Skin Plates**

The QA inspector performed ultrasonic testing (UT) at the completed joint penetration at the skin plates splices weld joints # ESD1 SA-77 A/E-36B, ESD1 SA77A A/E-34B, ESD1-SA233D D/F-3A, ESD1-SA233D E/F 6B, ESD1-SA233 E/F 25A, ESD1-SA216 J/K-7B, ESD1-SA216 J/K-8B and ESD1-SA216 J/K-9B. The QA inspector performed 10 % UT at random locations. The QA inspector found that welds areas tested appeared to be in compliance with the contract documents. See UT report TL\_6027 generated on this date.

The QA inspector performed UT at the completed joint penetration at the side plates splices weld joints # SEG-017A-002(jointing side plates SP19A/SP27A). The QA inspector performed 10 % UT at random locations. The QA inspector found that welds areas tested appeared to be in compliance with the contract documents. See UT report TL\_6027 generated on this date.

**Summary of Conversations:**

As noted above.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

---

---

# WELDING INSPECTION REPORT

*( Continued Page 2 of 2 )*

---

---

---

<b>Inspected By:</b>	Acuna,Alfredo	Quality Assurance Inspector
----------------------	---------------	-----------------------------

---

<b>Reviewed By:</b>	Cuellar,Robert	QA Reviewer
---------------------	----------------	-------------

---