

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-005419**Date Inspected:** 28-Jan-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yan Hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG segments**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

OBG outside assembly (OBG segment 3AE)

This QA observed ZPMC qualified welding personnel identified as Mr. Wang Li (044772) perform SMAW weld repair on weld joints identified as SEG-014A-039 and 40. ZPMC QC identified Mr. Wang Wei Ming was present to monitor the weld repair process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW-4G (4F)-FCM-repair.

This QA observed ZPMC qualified welding personnel identified as Mr. Hao Jian Xiang perform SMAW weld repair on weld joints identified as SEG-014*-031 and 032. ZPMC QC identified Mr. Wang Wei Ming was present to monitor the weld repair process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345-SMAW-4G (4F)-FCM-repair.

OBG outside assembly (OBG segment 4AE)

This QA observed ZPMC personnel removing one of the square tube cross braces on one of the floor beams in order to facilitate blasting and painting of the faying surfaces at the connection points.

No other significant work was observed on this segment while QA was present.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

OBG outside assembly (OBG segment 3BW)

This QA noted that this segment has been moved into the paint bay for blast and paint.

OBG outside assembly (OBG segment 3AW)

This QA observed ZPMC qualified welding personnel identified as Mr. Bi Lai Shu (045280) perform FCAW welding on weld joint identified as FB017-001-164. ZPMC QC identified Mr. Yang Diang was present to monitor the weld process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-TC-U4b-F-1.

This QA observed ZPMC qualified welding personnel identified as Mr. Bi Lai Shu (045280) perform SMAW welding on weld joint identified as FB017-001-165. ZPMC QC identified Mr. Yang Diang was present to monitor the weld process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214-B-U2.

This QA observed ZPMC qualified welding personnel identified as Mr. Yun Chuanshan (050316) perform FCAW welding on weld joint identified as FB025-001-164. ZPMC QC identified Mr. Yang Diang was present to monitor the weld process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-TC-U4b-F-1.

This QA observed ZPMC qualified welding personnel identified as Mr. Yun Chuanshan (050316) perform SMAW welding on weld joint identified as FB025-001-165. ZPMC QC identified Mr. Yang Diang was present to monitor the weld process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214-B-U2.

OBG outside assembly (OBG segments 4AW, 5CE and 3BE)

No significant work was observed on these segments while QA was present.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

only general conversation was held between QA and QC concerning this project.

WELDING INSPECTION REPORT

(*Continued Page 3 of 3*)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Hall,Steven	Quality Assurance Inspector
----------------------	-------------	-----------------------------

Reviewed By:	Carreon,Albert	QA Reviewer
---------------------	----------------	-------------