

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 70.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006224**Date Inspected:** 07-Apr-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1030**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1730**Contractor:** Japan Steel Works**Location:** Muroran, Japan**CWI Name:** Chung Fu Kuan**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower, Jacking and Deviation Saddles**Summary of Items Observed:**

On this date, 4/7/09, Caltrans OSM Quality Assurance (QA) Inspector Mike Brcic was present during the times noted above for observations relative to the work being performed on castings, in either the Fabrication shop #4 or Foundry Shop at Japan Steel Works.

W2E3 - Casting section idle, built up section is having the radii at plate ribs to cast stem prepared by grinding.

W2W2 - Magnetic Particle testing (MT) was done on areas ground to remove surface indications following first wet MT inspection.

W2W3 - Piece sitting idle, repairs are as welded.

T1-2 - Welders 08-5153 and 81-5438 are welding joints 8Y-5U-1 and 8Y-7U respectively. QCI verified amperes and preheat of welders, parameters were found to be in compliance to procedure SJ3012-5, contract documents and special provisions.

T1-3 - Weld procedure SJ3012-1-1, (surfacing of cast material) was used by welders #07-2941, 07-4510, and 07-4528, on joints 9Y-12U-2 (3rd layer), 9Y-7U (2nd layer), and 9Y-5U-2 (1st layer) respectively, all parameters set forth by contract documents and special provisions appeared to be met at this time.

E2E1 - Two men actively shaping by way of Carbon Arc, appears to be 90% complete.

E2W1 - Casting was in process of being moved to another location within Foundry.

Unless otherwise noted, all observations reported on this date appeared to be in general compliance with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Summary of Conversations:

No significant conversations to report on this day.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy, 1(510)385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Brcic,Michael	Quality Assurance Inspector
Reviewed By:	Lanz,Joe	QA Reviewer
