

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008443**Date Inspected:** 23-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Zhi Jiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Hiranch Patel, was present during the times noted above for observations relative to the work being performed.

Bay#2 Segment 1AAW

This QA inspector performed random VT after welding of the shim plate area. The member is identified as segment 1AAW. ZPMC QC-CWI Li Zhi Jiang and ABFJV Wang Wen Bin were present during observation

This QA inspector performed base metal thickness check by UT zero degree on all temporary attachment removal areas on deck plate, bottom plate and side plate. These areas previously tested and accepted by ZPMC Quality Control personnel. The member is identified as segment 1AAW. Thickness found within limit. Result Acceptable by ZPMC and CT The plate detail and plate number is designated as below:

Plate Detail- X191A/191B

Plate number- PL1460A- Corner assembly

Plate number- PL857A- Deck Plate

Plate number- PL857B- Deck Plate

Plate number- PL862A- Deck Plate

Plate number- PL872A- Deck Plate

Plate number- PL867B- Deck Plate

Plate number- PL877A- Deck Plate

Plate number- PL867A- Deck Plate

Plate number- PL857B- Deck Plate

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Plate number- PL862B- Corner assembly

Plate number- PL1465A-Side plate

Plate number- PL1473A- Side plate

Plate number- PL1454A- Bottom Plate.

Plate number- PL1475A- Side plate

Plate number- PL1465B- Side plate

Bay #2, Segment 1AAW

This QA inspector observed the following work in progress:

FCAW welding repair of shim plates at locations A07, A08, A09, A10 on Segment 1AAW. Welder is identified as 048433 (3G). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

SMAW welding of pipe locations A13/14 on Segment 1AAW. Welder is identified as 058242(4G/F). ZPMC QC-CWI is identified as Li Zhi Jiang . The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

| | | |
|----------------------|---------------|-----------------------------|
| Inspected By: | Patel,Hiranch | Quality Assurance Inspector |
| Reviewed By: | Prue,Erik | QA Reviewer |
