

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-010391**Date Inspected:** 05-Nov-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Chen Xi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Crossbeams**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Steve Hall was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

OBG CROSS BEAM CB1

This crossbeam appears to be complete and has been loaded on the ship.

OBG CROSS BEAM CB2

This crossbeam appears to be complete and has been loaded on the ship.

OBG CROSS BEAM CB3

This crossbeam appears to be complete and has been loaded on the ship.

OBG CROSS BEAM CB4

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

OBG CROSS BEAM CB5

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB6

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB7

This QA observed ZPMC Magnetic particle Testing (MT) technician perform MT on various weld joints. The technician appeared to be testing repaired areas of the welds.

OBG CROSS BEAM CB8

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB9

This QA observed ZPMC qualified welding personnel identified as 019006 perform FCAW welding on weld joint identified as CB202A-009-020. ZPMC QC identified as Mr. Liu Chuan Gang was present to monitor the welding process. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2132.

OBG CROSS BEAM CB10

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB11

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB12

This QA observed ZPMC qualified welding personnel identified as 069118 perform SMAW repair welding on various weld joints. ZPMC QC identified as Mr. Sun Yan Fei was present to monitor the welding process. Mr. Sun informed this QA that a majority of the repairs being performed today are under size welds. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

WPS-345-SMAW-3G (3F)-repair.

OBG CROSS BEAM CB13

This QA observed that ZPMC appears to be finished with the fit up of this crossbeam. No significant work was observed being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB14

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB15

This QA observed that ZPMC is continuing to fit the floor beam sections to both of the side panels and the intermediate panel. No other significant work was observed on this crossbeam during the time QA was present.

OBG CROSS BEAM CB16

This QA observed that no significant work was being performed on this crossbeam during the time QA was present.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

Inspected By:	Hall,Steven	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
