

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011451**Date Inspected:** 01-Jun-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	Xu Xian Ping	<b>CWI Present:</b>	Yes	No
<b>Inspected CWI report:</b>	Yes No N/A	<b>Rod Oven in Use:</b>	Yes No N/A	
<b>Electrode to specification:</b>	Yes No N/A	<b>Weld Procedures Followed:</b>	Yes No N/A	
<b>Qualified Welders:</b>	Yes No N/A	<b>Verified Joint Fit-up:</b>	Yes No N/A	
<b>Approved Drawings:</b>	Yes No N/A	<b>Approved WPS:</b>	Yes No N/A	
		<b>Delayed / Cancelled:</b>	Yes No N/A	
<b>Bridge No:</b>	34-0006	<b>Component:</b>	OBG Deck Panels	

**Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Stefan Holmes was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China.

QA inspector performed conventional Ultrasonic Testing (UT) Inspection on 12mm thick tube-to-plate T-joint CJP welds made on OBG Traveler railing brackets located in Trial Assembly area. Traveler railing brackets inspected and results are as follows:

TR2A-PP022 15% MT Tested; 15% UT Tested.  
TR5B-PP023 15% MT Tested; 15% UT Tested.  
TR5B-PP021 15% MT Tested; 15% UT Tested.  
TR5B-PP019 15% MT Tested; 15% UT Tested.  
TR2A-PP028 15% MT Tested; 15% UT Tested.  
TR2A-PP026 15% MT Tested; 15% UT Tested.  
TR6A-PP024 15% MT Tested; 15% UT Tested.  
TR5A-PP025 15% MT Tested; 15% UT Tested.  
TR6A-PP028 15% MT Tested; 15% UT Tested.  
TR5A-PP027 15% MT Tested; 15% UT Tested.  
TR6A-PP026 15% MT Tested; 15% UT Tested.  
TR1A-PP025 15% MT Tested; 15% UT Tested.  
TR2A-PP024 15% MT Tested; 15% UT Tested.

---

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

TR1A-PP021 15% MT Tested; 15% UT Tested.  
TR1A-PP019 15% MT Tested; 15% UT Tested.  
TR1A-PP027 15% MT Tested; 15% UT Tested.  
TR2A-PP020 15% MT Tested; 15% UT Tested.  
TR1A-PP023 15% MT Tested; 15% UT Tested.  
TR6A-PP022 15% MT Tested; 15% UT Tested.  
TR6A-PP020 15% MT Tested; 15% UT Tested.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

**Summary of Conversations:**

No relevant conversations.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Holmes,Stefan	Quality Assurance Inspector
----------------------	---------------	-----------------------------

---

<b>Reviewed By:</b>	Hall,Steven	QA Reviewer
---------------------	-------------	-------------