

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014820**Date Inspected:** 12-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, M. Manikandan was present during the time noted above for observations relative to the work being performed.

OBG # OUTSIDE YARD

This QA Inspector performed joint Survey Inspection along with ABF for the following Segment 10AW from Panel Point 86 to 88. Reports forwarded to team leader for further action.

Inspection details as follows

- 1) Plumpness and flatness measurements between Deck panel and deck panel diaphragm using right angle and 710mm straight edge.
- 2) Flatness measurement on Floor beam using 1.5M straight edge.
- 3) Flatness measurement on longitudinal weld joining deck panel and corner assembly deck panel using 600mm straight edge.
- 4) Flatness measurement on longitudinal weld joining Side panel and corner assembly Side panel using 600mm straight edge.

OBG # SEGMENT 9CW

This QA inspector performed visual inspection and dimensional checks on weld access cope holes on OBG

WELDING INSPECTION REPORT

(*Continued Page 2 of 2*)

Segment 9CW. Inspection was been performed against ABF inspection report CWAHIR-9CW-01 dated 5th April 2010. The exhibited radii edge discontinuities has been recorded and forwarded to team leader for further action.

OBG # SEGMENT 9BE

This QA inspector performed visual inspection and dimensional checks on weld access cope holes on OBG Segment 9CW. Inspection was been performed against ABF inspection report CWAHIR-9BE-01 dated 22nd Jan 2010. The exhibited radii edge discontinuities has been recorded and forwarded to team leader for further action.

OBG # SEGMENT 9CE

This QA inspector performed visual inspection and dimensional checks on weld access cope holes on OBG Segment 9CW. Inspection was been performed against ABF inspection report CWAHIR-9CE-01 dated 12th April 2010. The exhibited radii edge discontinuities has been recorded and forwarded to team leader for further action.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

Inspected By:	Manikandan,Murugan	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
