

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/Ala Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016109**Date Inspected:** 06-Aug-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** See below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 11

This QA Inspector randomly observed the following work in progress in Bay 11:

FCAW welding of weld joints BK004A-017-A7-125, 126 located on PCMK bike path beam, web to stiffener. Welder was identified as 042218. QC was identified as ZPMC CWI Xu Le Feng (QC1). Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Ma Qian Li (QCA1), who was not a CWI. Welding variables recorded by QCA1 appeared to comply with WPS-B-T-2133.

FCAW welding of weld joints BK004A-017-A7-063, 064 located on PCMK bike path beam, web to stiffener. Welder was identified as 208649. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA1, who was not a CWI. Welding variables recorded by QCA1 appeared to comply with WPS-B-T-2133.

FCAW welding of weld joints BK004A-020-A6-074 located on PCMK bike path beam, web to flange. Welder was identified as 053316. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA1, who was not a CWI. Welding variables recorded by QCA1 appeared to comply with WPS-B-T-2131.

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

SMAW welding of weld joint WSD1-TL5-4B/F-23 located on PCMK west tower, lift 5, internal connection plates.

Alternating welders were identified as 067588, 066326. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Zhao mao Mao (QCA2), who was not a CWI. Welding variables recorded by QCA2 appeared to comply with WPS-B-T-3213-TC-U4c. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

SMAW welding of weld joint WSD1-TL5-4E/F-20B located on PCMK west tower, lift 5, internal connection plates. Alternating welders were identified as 068924, 066416. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA2, who was not a CWI. Welding variables recorded by QCA1 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

SMAW welding of weld joint WSD1-TL5-4B/F-29A located on PCMK west tower, lift 5, external connection plates. Alternating welders were identified as 066236, 070432. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA2, who was not a CWI. Welding variables recorded by QCA2 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

SMAW welding of weld joint WSD1-TL5-4B/F-30A located on PCMK west tower, lift 5, external connection plates. Alternating welders were identified as 066416, 068924. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA2, who was not a CWI. Welding variables recorded by QCA2 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

SMAW welding of weld joint ESD1-TL5-2B/F-12B located on PCMK east tower, lift 5, internal connection plates.

Alternating welders were identified as 040690, 202100. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA2, who was not a CWI. Welding variables recorded by QCA2 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

SMAW welding of weld joints ESD1-TL5-2F/F-10, 11 located on PCMK east tower, lift 5, internal connection plates. Welders were identified, respectively, as 040614, 040667. QC was identified as QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA2, who was not a CWI. Welding variables recorded by QCA2 appeared to comply with WPS-B-T-3313-TC-P5. Also at this location and appearing to be monitoring the welding operation was ABF Representative Cui Zheng Hua.

Bay 10

This QA Inspector randomly observed the following work in progress in Bay 10:

SMAW welding of weld joint SSD1-TL5-1B-F-12 located on PCMK south tower, lift 5, internal connection plates.

Alternating welders were identified as 057266, 056364, 057266. QC was identified at QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was ZPMC QC Li Peng Fei (QCA3), who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3213-TC-U4c.

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

SMAW welding of weld joint SSD1-TL5-1F-F-25B located on PCMK south tower, lift 5, internal connection plates. Welder was identified as 050289. QC was identified at QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA3, who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

SMAW welding of weld joint SSD1-TL5-1E-F-3 located on PCMK south tower, lift 5, internal connection plates. Welder was identified as 500363. QC was identified at QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA3, who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3313-TC-P5. Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

SMAW welding of weld joint NSD1-TL5-3B-F-11 located on PCMK north tower, lift 5, internal connection plates. Alternating welders were identified as 066413, 067656. QC was identified at QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA3, who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3213-TC-U4c. Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

SMAW welding of weld joints NSD1-TL5-3B-F-28A, 29A located on PCMK north tower, lift 5, internal connection plates. Alternating welders at both welds were identified as 037780, 037998. QC was identified at QC1. Welding Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA3, who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

SMAW welding of weld joint NSD1-TL5-3F-F-21A located on PCMK north tower, lift 5, internal connection plates. Alternating welders were identified as 066418, 066763. QC was identified at QC1. Assisting QC1 at this location and appearing to be monitoring the welding and recording data was QCA3, who was not a CWI. Welding variables recorded by QCA3 appeared to comply with WPS-B-T-3213-TC-U5b. Also at this location and appearing to be monitoring the welding operation was ABF Representative Chi Zheng Hua.

Heavy Dock

This QA Inspector randomly observed the following work being performed on the Heavy Dock:

This QA Inspector observed no apparent welding related work was being performed on the Heavy Dock. All 4 tower lift's 3 were connected and positioned on a base pedestal at end of the heavy dock. All 4 tower lift's 2 were positioned horizontally on stanchions on the deck at the end of the heavy dock. ZPMC personnel were working at various tower, lift's 2 appearing to be removing worker staging and temporarily bolted splice plate assemblies. ABF Representative Kang Li informed this QA Inspector that no welding work was being performed during this night shift.

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As noted above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Micheal Ng, 159-2184-5703, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer
