

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016950**Date Inspected:** 09-Sep-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Yu Dong Ping
Inspected CWI report: Yes No N/A
Electrode to specification: Yes No N/A
Qualified Welders: Yes No N/A
Approved Drawings: Yes No N/A

CWI Present: Yes No
Rod Oven in Use: Yes No N/A
Weld Procedures Followed: Yes No N/A
Verified Joint Fit-up: Yes No N/A
Approved WPS: Yes No N/A
Delayed / Cancelled: Yes No N/A

Bridge No: 34-0006**Component:** Tower & OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

TOWER JETTY

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 006625

Visual Inspection Testing (VT)

This QA inspector performed VT of the area previously tested and accepted by ZPMC Quality Control personnel. The member is identified as Tower Component. The identified component designations reviewed are as follows:

LIFT-3 TOWER CROSS BRACING GUSSET PLATE

WD1 – GUSA3 – 3 – 99M – W –4A/B

Magnetic Particle Testing (MT)

This QA inspector performed MT of the area previously tested and accepted by ZPMC Quality Control personnel.

This QA Inspector generated an MT report for this date. The member is identified as Tower Component. The weld designation reviewed as follows:

LIFT-3 TOWER CROSS BRACING GUSSET PLATE

WD1 – GUSA3 – 3 – 99M – W –4A/B

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

BAY#10

ORTHOTROPIC BOX GIRDER (OBG) AT BAY#10

This QA Inspector observed the following work in progress

Submerged Arc Welding (SAW):

Weld joint # 02 located on SEG3007AC. Welder is identified as 058100. ZPMC Quality Control (QC) Inspector is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2221 – B – U3c – S – 2. (See attached photo)

Weld joint # 292 located on BP3094 – 001 Welder is identified as 207745. ZPMC Quality Control (QC) Inspector is identified as Sun Tian Liang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2221 – B – L2c – S – 2.

Shielded Metal Arc Welding (SMAW):

Weld repair of a weld joint # 03 located on SEG3007AC. Welder is identified as 048047. ZPMC Quality Control (QC) Inspector is identified as Zhang Lin. The welding variables recorded by QC appeared to comply with the WPS – 345 – SMAW – 1G (1F) – FCM – REPAIR – 1.

BAY#11

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 006627

Ultrasonic Testing (UT)

This QA inspector performed UT of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as Tower Component. The weld designation reviewed as follows:

LIFT-5 INTERNAL SPLICE PLATE – GREEN TAG#14325

WSD1 – SPSA5 – 20 – 1A/B; 2A/B

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint # 17 located on East tower Lift-5 Grillage Assembly ESD1 – TL5 – 2B/F. Welder is identified as 040611. ZPMC Quality Control (QC) Inspector is identified as Shang Hai Long. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3213 – Tc – U4c. (See attached photo)

Weld joint # 14 located on East tower Lift-5 Grillage Assembly ESD1 – TL5 – 2B/F. Welder is identified as 040723. ZPMC Quality Control (QC) Inspector is identified as Shang Hai Long. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3213 – Tc – U4c.

ORTHOTROPIC BOX GIRDER (OBG) AT BAY#11

This QA Inspector observed the following work in progress

Fluxcored Arc Welding (FCAW):

Weld joint # 13 located on Bottom plate BP3091 – 001. Welder is identified as 049220. ZPMC Quality Control

WELDING INSPECTION REPORT


(Continued Page 3 of 3)

(QC) Inspector is identified as Liu Dao Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Weld joint # 32 located on Bottom plate BP3091 – 001. Welder is identified as 040759. ZPMC Quality Control (QC) Inspector is identified as Liu Dao Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Weld joint # 25 located on Bottom plate BP3091 – 001. Welder is identified as 053316. ZPMC Quality Control (QC) Inspector is identified as Liu Dao Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng - 15921845703, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Sandeep	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
