

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-017326**Date Inspected:** 28-Sep-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:****CWI Present:**

Yes No

Inspected CWI report: Yes No N/A**Rod Oven in Use:**

Yes No N/A

Electrode to specification: Yes No N/A**Weld Procedures Followed:**

Yes No N/A

Qualified Welders: Yes No N/A**Verified Joint Fit-up:**

Yes No N/A

Approved Drawings: Yes No N/A**Approved WPS:**

Yes No N/A

Delayed / Cancelled:

Yes No N/A

Bridge No: 34-0006**Component:** OBG, Tower**Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Christopher D'souza was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed and/or found the following:

Outside yard

B-CWR 1955 Rev 1

This QA Inspector was notified via email for verification of B – CWR1773 R1 at 0840 hours the following was observed:

- The component for verification was identified as CB16
- Weld Repair was required on location where rejectable indication was observed by Ultrasonic Testing (UT) weld numbers CB202A-016-002, 014
- ZPMC QC Zhen Zhi Wei was present on site to direct and record all repair work.
- Weld Repair was to be carried out as per WPS-SPCM-345-SMAW-3G(3F)-Repair 1

Trial Assembly

B-CWR 1843 Rev 0

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA Inspector was notified via email for verification of B – CWR1843 R0 at 0940 hours the following was observed:

- The component for verification was identified as OBE10, 11 and OBW10, 11
- Base metal repair was required after removal of temporary between Bike path and suspender brackets on OBW and OBE lifts 10 and 11
- ZPMC CWI Luan Zhao Gang was present on site to direct and record all repair work.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Dsouza, Christopher	Quality Assurance Inspector
----------------------	---------------------	-----------------------------

Reviewed By:	Carreon, Albert	QA Reviewer
---------------------	-----------------	-------------