

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-018338**Date Inspected:** 10-Nov-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhu Feng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** TOWER & OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

TOWER JETTY

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Repair welding of weld joint # 06 located on West tower Lift-4 Skin 'E', 119 M Backfill plate WSD1 – FESA4 – 4B/F as per the weld repair report # T-WR3740. Welder is identified as 040690. ZPMC Quality Control (QC) Inspector is identified Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS – 485 – SMAW – 2G (2F) – Repair – 1.

Repair welding of weld joint # 07 located on West tower Lift-4 Skin 'E', 119 M Backfill plate WSD1 – FESA4 – 4B/F as per the weld repair report # T-WR3741. Welder is identified as 040690. ZPMC Quality Control (QC) Inspector is identified Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS – 485 – SMAW – 2G (2F) – Repair – 1. (See attached photo)

Repair welding of weld joint # 06 located on West tower Lift-4 Skin 'E', 119 M Backfill plate WSD1 – FESA4 – 4B/F as per the weld repair report # T-WR3740. Welder is identified as 046769. ZPMC Quality Control (QC)

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Inspector is identified Sun Zi Wang. The welding variables recorded by QC appeared to comply with the WPS – 485 – SMAW – 2G (2F) – Repair – 1.

BAY#10

This QA Inspector observed the following work in progress

Witness of Ultrasonic Testing (UT)

This QA inspector Witnessed UT performed by ABF Quality Control personnel. The member is identified as TOWER Component. The component and weld designation identified as follows:

SOUTH TOWER GRILLAGE COVER PLATE

SSD1 – TL5 – 1B/F – 50A

ORTHOTROPIC BOX GIRDER (OBG) AT BAY#10

This QA Inspector observed the following work in progress

Fluxcored Arc Welding (FCAW):

Weld joint # 034 located on Bike Path, BK004A3 – 027. Welder is identified as 040302. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Weld joint # 088 located on Bike Path, BK004A8– 026. Welder is identified as 040533. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2133.

Weld joint # 024 located on Bike Path, BK004A4 – 027. Welder is identified as 040302. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Shielded Metal Arc Welding (SMAW):

Weld joint # 102 located on Bike Path, BK004A3 – 028. Welder is identified as 052493. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2114.

Weld joint # 083 located on Bike Path, BK004A4 – 028. Welder is identified as 052493. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2112.

Weld joint # 102 located on Bike Path, BK004A4 – 028. Welder is identified as 052493. ZPMC Quality Control (QC) Inspector is identified as Li Jun. The welding variables recorded by QC appeared to comply with the WPS – B – P – 2114.

BAY#11

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Weld joint # 6B located on Lift-5 bracket SD1 – BRSA5 – 1. Welder is identified as 054460. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3212 – TC – U5b.

Weld joint # 1B located on Lift-5 bracket ND1 – BRSA5 – 2. Welder is identified as 040724. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3213 – TC – U5b. (See attached photo)

Weld joint # 6B located on Lift-5 bracket SD1 – BRSA5 – 1. Welder is identified as 044541. ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3212 – TC – U5b.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Ho- 15002048250, who represents the Office of Structural Materials for your project.

Inspected By: Kumar,Sandeep

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer