

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020514**Date Inspected:** 11-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Sha Zi**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

Bay #19

Weld joint 030 Located on Side plate to channel of Bike path BK 004A1-014. Welder is identified as 062755. ZPMC Quality Control Inspector (QC) is identified as Gao Xing Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint 047 Located on Side plate to channel of Bike path BK 004A1-014. Welder is identified as 062755. ZPMC Quality Control Inspector (QC) is identified as Gao Xing Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint 002, 007 Located on Closure plate to Deck plate of Bike path BK 004A-013. Welder is identified as 062732. ZPMC Quality Control Inspector (QC) is identified as Gao Xing Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2232-ESAB.

Weld joint 047 Located on Side plate to channel of Bike path BK 004A1-014. Welder is identified as 062732.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

ZPMC Quality Control Inspector (QC) is identified as Gao Xing Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2233-ESAB.

Bay #16

Weld joint 009, 010 Located on Bottom plate to stiffener, BP3095-001. Welder is identified as 068858. ZPMC Quality Control Inspector (QC) is identified as Gao Xing Hai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Bay #14

This QA Inspector observed the following work in progress

Flux Cored Arc Welding (FCAW)

Weld joint 054, Located on Lift 14E, Anchor plate to Floor beam in P.P 127 mtr., SEG3019L. Welder is identified as 067520. ZPMC Quality Control Inspector (QC) is identified as Xie Ming Feng. The welding variables recorded by QC appeared to comply with the WPS-B-T-2132-ESAB.

Shielded Metal Arc Welding (SMAW):

Weld joint 001, Located on Deck panel to Diaphragm, SEG3009. Welder is identified as 067571. ZPMC Quality Control Inspector (QC) is identified as Xie Ming Feng. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-B-U2-FCM-1.


Weld joint 001, Located on Deck panel to Diaphragm, SEG3009. Welder is identified as 067572. ZPMC Quality Control Inspector (QC) is identified as Xie Ming Feng. The welding variables recorded by QC appeared to comply with the WPS-B-P-2211-B-U2-FCM-1.

For further information see below pictures:-

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Hu (15002048250), who represents the Office of Structural Materials for your project.

Inspected By: Baskar, Govindarajan

Quality Assurance Inspector

Reviewed By: Clifford, William

QA Reviewer