

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: xx.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020531**Date Inspected:** 11-Aug-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China**CWI Name:** Mr. Zhu Zhong Hai.**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Trial Assembly**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Raghavendra Reddy was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA Inspector observed the following work in progress:

SEGMENT # 9W:

Flux Cored Arc Welding (FCAW) of weld joint OBW9C-002(9CW+9DW, SP-SP), And Welding Repair Report(WR),B-WR14503, Welder is identified as 202384. ZPMC Quality Control (QC) is identified as Mr. Zho peng. The welding variables appeared to comply with the Applicable WPS: WPS-345-FCAW-3G-FCM-REPAIR-1.

Shielded Metal Arc Welding (SMAW) welding of welds joint SP636-001-032,(I Rib, 9BW-9CW).And Welding Repair Report(WR),B-WR14510, Welder is identified as 067904. ZPMC Quality Control (QC) is identified as Mr. Zhou Peng. The welding variables appeared to comply with the Applicable WPS-345-SMAW-4G-FCM-Repair.

SMAW welding of weld joint DP685-001-021(I Rib,9BW-9CW). And Welding Repair Report (WR) B-WR-14513 Welder is identified as 045196. ZPMC Quality Control (QC) is identified as Mr. Shi Lei . The welding variables appeared to comply with the Applicable WPS-345-SMAW-3G-FCM-Repair.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SMAW welding of weld joint DP686-001-13~18/DP687-001-07~12 (9DW-9EW,I to DP). Welder is identified as 067572. ZPMC Quality Control (QC) is identified as Mr. She Lei. The welding variables appeared to comply with the Applicable WPS-B-T-4114-1.

SMAW welding of weld joint DP673-001-13~18/DP674-001-07~12 (9DW-9EW,I to DP). Welder is identified as 067665. ZPMC Quality Control (QC) is identified as Mr. She Lei. The welding variables appeared to comply with the Applicable WPS-B-T-4114-1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng (15921845703), who represents the Office of Structural Materials for your project.

Inspected By:	Tharikoppada,Reddy	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer
