

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020615**Date Inspected:** 08-Dec-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Mr. Geng Wei
Inspected CWI report: Yes No N/A
Electrode to specification: Yes No N/A
Qualified Welders: Yes No N/A
Approved Drawings: Yes No N/A

CWI Present: Yes No
Rod Oven in Use: Yes No N/A
Weld Procedures Followed: Yes No N/A
Verified Joint Fit-up: Yes No N/A
Approved WPS: Yes No N/A
Delayed / Cancelled: Yes No N/A

Bridge No: 34-0006**Component:** BAY 14 OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Robert A. DeArmond was present during the time noted above and conducted observations relative to the work being performed.

OBG BAY 14

This QA Inspector observed the following work in progress:

ZPMC personnel heat straightening Orthotropic Box Girder (OBG) member identified as Lift 13CE; VP3008A-001 weld joint(s) 032. Distortion appeared to be caused by welding of the material. ZPMC Quality Control (QC) inspector identified as Mr. Shao Jian Yuan was present to monitor the heat straightening process. The heat straightening appeared to comply with Heat Straightening Report HSR1 (B)-9831 (R787-QCP-1101) dated 11-11-2010.

SAW welding of complete joint penetration weld joint(s) located on Deck Plate identified as Segment 3020* DP3176 to 3177 weld number(s) 010. Welder is identified as welder no. 045265. The welding variables recorded by ZPMC QC identified as Mr. Shao Jian Yuan appeared to comply with applicable WPS(s) WPS-B-T-2221-B-L2C-S-2.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

SMAW welding of complete joint penetration weld joint(s) located on Segment 3013AD Floor Beam to Side Panel weld number(s) 034. Welder is identified as welder no (s). 051348. The welding variables recorded by ZPMC QC identified as Sun Tian Liang appeared to comply with applicable WPS(s) WPS-B-P-2214-TC-U4b-FCM 1.

During random in process inspection of Orthotropic Box Girder (OBG) member identified as DP3104-001 weld number(s) 009 this QA Inspector observed weld repair of complete joint penetration weld joint(s). ZPMC Quality Control personnel previously tested and rejected sections of weld within weld no. 009. Weld joint consisted of SMAW welding of complete joint penetration weld joint(s). Welder is identified as welder no (s). 051359. The welding variables recorded by ZPMC QC identified as Zong Guo Hui appeared to comply with applicable WPS(s) WPS-345-SMAW-1G (1F)-FCM-Repair, WPS-345-4G (4F)-FCM-Repair and (WR18494).

During random in process inspection of Orthotropic Box Girder (OBG) member identified as DP3103-001 weld number(s) 301 this QA Inspector observed weld repair of complete joint penetration weld joint(s). ZPMC Quality Control personnel previously tested and rejected sections of weld within weld no. 301. Weld joint consisted of SMAW welding of complete joint penetration weld joint(s). Welder is identified as welder no (s). 051359. The welding variables recorded by ZPMC QC identified as Zong Guo Hui appeared to comply with applicable WPS(s) WPS-345-SMAW-1G (1F)-FCM-Repair, WPS-345-4G (4F)-FCM-Repair and (CWR18495).


During random in process inspection of Orthotropic Box Girder (OBG) member identified as DP3103-001 weld number(s) 009 this QA Inspector observed weld repair of complete joint penetration weld joint(s). ZPMC Quality Control personnel previously tested and rejected sections of weld within weld no. 009. Weld joint consisted of SMAW welding of complete joint penetration weld joint(s). Welder is identified as welder no (s). 051359. The welding variables recorded by ZPMC QC identified as Zong Guo Hui appeared to comply with applicable WPS(s) WPS-345-SMAW-1G (1F)-FCM-Repair, WPS-345-4G (4F)-FCM-Repair and (WR18496).

During random in process inspection of Orthotropic Box Girder (OBG) member identified as DP3103-001 weld number(s) 301 this QA Inspector observed weld repair of complete joint penetration weld joint(s). ZPMC Quality Control personnel previously tested and rejected sections of weld within weld no. 301. Weld joint consisted of SMAW welding of complete joint penetration weld joint(s). Welder is identified as welder no (s). 051359. The welding variables recorded by ZPMC QC identified as Zong Guo Hui appeared to comply with applicable WPS(s) WPS-345-SMAW-1G (1F)-FCM-Repair, WPS-345-4G (4F)-FCM-Repair and (CWR18497).

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

As mentioned above between QA and QC concerning this project

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Jim Devy 150-002-6784, who represents the Office of Structural Materials for your project.

Inspected By: DeArmond,Robert

Quality Assurance Inspector

Reviewed By: Riley,Ken

QA Reviewer