

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-020962**Date Inspected:** 19-Feb-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island**Location:** Shanghai**CWI Name:** Tian Lei**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector R. Hernandez was present during the time noted above and conducted observations relative to the work being performed.

The QA Inspector randomly observed the following work in progress:

Bay Number 1

This inspector observed ZPMC QC personnel performing fit-up and tack welding of the following cable tray components identified as SA6508A (5 pieces), SA6508E (7 pieces), SA6508C (4 pieces), SA6508B (5 pieces).

Bay Number 3

This inspector observed ZPMC QC personnel performing fit-up and bevel edge preparation of the following piece numbers for the component identified as EP3017, X7017A, X7017B, X7017C per welding detail WD571AG @ PP 118 to PP120-80 per joint detail PJP (TC-P4-GF) a 45 degree 12 mm opening with a 6mm landing.

Bay Number 6

The following components were in the above noted bay: RL3011A, RL3011B, RL3015A, RL3016A, RL3016B, RL3017A, RL3017B, RL3343A, & RL3343B. At the time this inspector was in this bay, this inspector did not observe any work being performed on these components.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Bay Number 8

The following components were in the above noted bay: BK4A-060, BK4A-059, & BK4A-063. At the time this inspector was in this bay, this inspector did not observe any work being performed on these components.

This inspector on this day also entered daily reports into PMIV.

Unless otherwise noted above all items observed on this day appeared to be in general compliance with the applicable contract documents

Summary of Conversations:

Pertinent conversations are included in the body of the report.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 1500-0042-02372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Rene	Quality Assurance Inspector
----------------------	----------------	-----------------------------

Reviewed By:	Hall,Steven	QA Reviewer
---------------------	-------------	-------------