

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023158**Date Inspected:** 28-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite**CWI Name:** John Pagliero**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** SAS OBG**Summary of Items Observed:**

Quality Assurance inspector (QA) Douglas Frey was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

1. 10W 11W Longitudinal Stiffener #3
2. 10W 11W Longitudinal Stiffener #4
3. 9W 10W D (outside)
4. 6W PP 35W4 Lifting Lug Holes 2- 4 Visual Inspection
5. 8W PP70.5 W5 DAH Longitudinal Stiffeners Visual Inspection
6. 6W PP35 W4 Lifting Lug Holes 2-4 Magnetic Particle Inspection
7. 8W PP70.5 W5 DAH Longitudinal Stiffeners Magnetic Particle Inspection
8. 6W PP35 W4 Lifting Lug Holes 2-4 Ultrasonic Inspection
9. 8W PP70.5 W5 DAH Longitudinal Stiffeners Ultrasonic Inspection

1. 10W 11W Longitudinal Stiffener #3

The QA Inspector periodically observed the in process Shielded Metal Arc Welding (SMAW) being performed in the 3G vertical position by ABF welder Hua Qiang Hwang on the Longitudinal Stiffener (LS)#3. QC inspector John Pagliero was noted to be present in order to monitor the progress and ensure the welding parameters were within the established Welding Procedure Specification (WPS). The work continued throughout the QA Inspector's shift. The QA Inspector noted that the work was completed on this date and appeared to be in general

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

conformance with the contract documents.

2. 10W 11W Longitudinal Stiffener#4

The QA Inspector periodically observed the in process SMAW being performed in the 3G vertical position by ABF welder Jin Pei Wang on the LS#4. QC inspector Steve McConnell was noted to be present in order to monitor the progress and ensure the welding parameters were within the established WPS. The QA Inspector randomly observed the welder throughout the day and noted that the work was in progress at the end of the QA Inspector's shift. The QA Inspector noted that the work appeared to be in general conformance with the contract documents.

3. 9W 10W D (outside)

The QA Inspector noted and periodically observed ABF welding operators Jimmy Zhen and Song Tao Huang performing Flux Core Arc Welding w/gas (FCAW-G) operations on face D outside of the OBG. The QA Inspector observed the QC inspector John Pagliero as being present in order to monitor the progress and ensure the welding parameters were within the established WPS. The work progressed throughout the QA Inspector's shift. The QA Inspector noted that the work appeared to be progressing in general conformance with the contract documents.

4. 6W PP35 W4 Lifting Lug Holes 2-4 Visual Inspection

The QA Inspector performed a Visual Inspection (VT) of Lifting Lug Hole's (LLH) 2-4 located at 6W PP35 W4 outside of the OBG. The QA Inspector tested the weld to verify the weld and testing by the QC Inspector meet the requirements of the contract documents. The QA Inspector noted that the work appeared to be free of defects and was found to be acceptable and in general conformance with the contract documents.

5. 8W PP70.5 W5 DAH Longitudinal Stiffeners Visual Inspection

The QA Inspector performed a VT on the Deck Access Hole (DAH) LS's located at 8W PP70.5 W5 E & W. The QA Inspector tested the weld to verify the weld and testing by the QC Inspector meet the requirements of the contract documents. The QA Inspector noted that the work appeared to be free of defects and was found to be acceptable and in general conformance with the contract documents.

6. 7W PP35 W4 Lifting Lug Holes 2-4 Magnetic Particle Inspection

The QA Inspector performed a Magnetic Particle Test (MT) on the LLH's 2-4 identified as 6W PP35 W4. The QA Inspector tested 10% of the weld to verify the weld and testing by QC meet the requirements of the contract documents. . The QA Inspector noted that the work appeared to be free of defects and was found to be acceptable and in general conformance with the contract documents.

7. 8W PP70.5 W5 DAH Longitudinal Stiffeners Magnetic Particle Inspection

The QA Inspector performed a Magnetic Particle Test (MT) on the LS's E&W located at 8W PP70.5 W5. The QA Inspector tested 10% of the weld to verify the weld and testing by QC meet the requirements of the contract

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

documents. The QA Inspector noted that the work appeared to be free of defects and was found to be acceptable and in general conformance with the contract documents.

8. 7W PP35 W4 Lifting Lug Holes 2-4 Ultrasonic Inspection

The QA Inspector performed an Ultrasonic Inspection (UT) on the LLH's 2-4 identified as 6W PP35 W4. The QA Inspector tested 10% of the weld to verify the weld and testing by QC meet the requirements of the contract documents. . The QA Inspector noted that the work appeared to be free of defects and was found to be acceptable and in general conformance with the contract documents.

9. 8W PP70.5 W5 DAH Longitudinal Stiffeners Ultrasonic Inspection

The QA Inspector performed Ultrasonic Testing on the DAH LS's located at 8W PP70.5 W5. The QA Inspector utilized a G.E./Krautkramer USN 60. The QA Inspector also utilized the UT Procedure identified as SE-UT-D1. 5-CT-100 Rev.4 during the examination. Upon completion of the testing, it was noted by the QA Inspector that no indications were present and the work was found to be acceptable.

Summary of Conversations:

As noted above



Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy 510-385-5910, who represents the Office of Structural Materials for your project.

Inspected By: Frey, Doug

Quality Assurance Inspector

Reviewed By: Levell, Bill

QA Reviewer