

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024519**Date Inspected:** 17-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Jobsite**CWI Name:** William Sherwood**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** SAS OBG**Summary of Items Observed:**

Quality Assurance inspector (QA) Douglas Frey was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

1. 9E PP77 E3 Lifting Lug Holes #1 and 3
2. 9W PP76 W4 Lifting Lug Holes #1 and 3
3. 2E PP18 E2.5 Storm Ties
4. Lifting Lug Lamination Scan (UT)

1. 9E PP77 E3 Lifting Lug Holes #1 and 3

The QA Inspector made periodic observations of ABF welder Jorge Lopez performing Shielded Metal Arc Welding (SMAW) in the 4G overhead position on Lifting Lug Holes (LLH) #1 and 3 located at 9E PP77 E3. The QA Inspector observed the QC Inspector Fred Von Hoff as being present in order to monitor the progress and ensure the welding parameters were in compliance pertaining to ABF-WPS-D15-1110A Rev. 1. The work was completed on this date and the QA Inspector noted that the work appeared to be in general conformance with the contract documents.

2. 9W PP76 W4 Lifting Lug Holes #1 and 3

The QA Inspector made periodic observations of ABF welder Fred Kaddu performing SMAW in the 4G overhead

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

position on LLH's #1 and 3 located at 9W PP76 W4. The QA Inspector observed the QC Inspector William Sherwood as being present in order to monitor the progress and ensure the welding parameters were in compliance pertaining to ABF-WPS-D15-1110A Rev. 1. The work is in progress and the QA Inspector noted that the work appeared to be in general conformance with the contract documents.

3. 2E PP18 E2.5 Storm Ties

The QA Inspector randomly observed ABF welder Rick Clayborn performing SMAW in the 1G Flat position on the Storm Ties for the temporary "Catwalk" located at 2E PP18 E2.5 and 3E PP19 E2.5. The QA Inspector observed the QC Inspector Jesse Cayabyab as being present in order to monitor the progress and ensure the welding parameters were in compliance pertaining to ABF-WPS-D15-F2200-2. The work was completed on this date and the QA Inspector noted that the work appeared to be in general conformance with the contract documents.

4. Lifting Lug Lamination Scan (UT)

The QA Inspector randomly tested areas adjacent to Lifting Lugs attached to the OBG floor beams at various pannel points. The scan was performed in the defined UT area as per submittal 1635 Rev. 00. The work is in progress and the QA Inspector noted that the work appeared to be in general conformance with the contract documents.

Summary of Conversations:

At the beginning the shift the QA Inspector met with QC Inspector William Sherwood and discussed the welders assignments and locations for the shift to include pending issues, ongoing work and required testing.



Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy 510-385-5910, who represents the Office of Structural Materials for your project.

Inspected By: Frey, Doug

Quality Assurance Inspector

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Reviewed By: Levell,Bill

QA Reviewer