

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025595**Date Inspected:** 27-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the Self-Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

SHIP # 19, OBG SEGMENT 13AE

During random in process inspection this QA Inspector observed that ZPMC personnel were installing traveler rail bracket on Side Panel (SP) of OBG segment 13AE. See attached photograph for more details.

SHIP # 19, OBG SEGMENT 14W

This Quality Assurance Inspector (QA) performed Visual Testing (VT) review of randomly selected welds and base metal of Side Panel, Bottom Panel, Edge Panel and Deck Panel located on OBG segment 14W. The following issue(s) have been noted.

Longitudinal linear indications were observed on temporary attachment removal area on the stiffeners of top Anchorage plate (AP) 3023A at FL3 area of segment 14W during witness with AB/F Magnetic Particle Testing (MT) personnel. See attached photograph for more details.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract

---

---



# WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

---

documents.



## Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang : 15000422372, who represents the Office of Structural Materials for your project.

---

**Inspected By:** Gaikwad,Umesh

Quality Assurance Inspector

---

**Reviewed By:** Peterson,Art

QA Reviewer