

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:** Casey, William**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-029703**Date Inspected:** 20-May-2013**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1100**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Job Site**CWI Name:** As noted below**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** SAS OBG**Summary of Items Observed:**

Quality Assurance Inspector (QA) Douglas Frey was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

This QA Inspector performed a Deck survey of the surface condition of "A" deck from OBGs 9W PP74 W3-W4 to 14W PP127 W3-W4. This inspection was conducted in conjunction with Smith Emery Quality Control personnel and impact sites as well as arc strikes and any irregularities was measured for depth and length as well as location and recorded for a repair procedure.

This QA Inspector randomly observed ABF welding personnel perform repair operations on "A" deck survey indications at the following locations;

#49 – 11E PP91-D5/W10/L22-RWR201305-006

#45 – 10E PP76-D/4W5/L10 –RWR201305-006

#56C – 12E PP114-D2/W20/L30-RWR201305-006

#68 – 13E PP123-D2/W6/L75 – RWR201305-006

#71A – 13E PP124-D5/W10/L60-RWR201305-007

This QA observed QC Inspector William Sherwood and Salvador Merino performing welding parameter checks such as voltage, amps, electrodes and preheats throughout the day. Non-Destructive Testing methods utilized by the QC Inspectors were Visual Testing (VT), Magnetic Particle Testing (MPT). QC Inspectors were observed performing inspection per applicable code and or contract criteria. Unless otherwise noted, all work observed on

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

this date appeared to generally comply with the contract documents.

Summary of Conversations:

Conversations on this date were relevant to work performed.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Gary Thomas 916-764-6027 , who represents the Office of Structural Materials for your project.

Inspected By:	Frey,Doug	Quality Assurance Inspector
Reviewed By:	Reyes,Danny	QA Reviewer
