CURRENT CONDITION

PROPOSED SOIL NAIL WALL

Driver's view, south of Willow Avenue.

FIGURE 3.13-2

VISUAL SIMULATION #1

Contra Costa 80