

Revised June 2001

Route 905

Cactus Road Noise-Sensitive Receiver Locations Relative to the Freeway North Alignment Alternative

Figure 4-42