

Bent Locations of Impacted Areas San Rafael Viaduct

FIGURE 7