Federal Fiscal Year 2009/2010 Bridge Preventive Maintenance Program
Mendocino County Department of Transportation

Priority (Lowest Number Is Top Priority)	County Location	Implementing Agency	Bridge number from Inspection Report	Local Agency Bridge ID	Facility Carried	Feature Intersected	Location	Sufficiency Rating	SD/FO Status	Work Description	Deck Area (ft^2)	Total Particip. Cost	Unit Cost ($/$ft^2$)	Federal Share	Running Fed Summary	Local Share	Running Local Share
1	N. CA	MCDOT	Develop BPMP								1	30,000	30,000.00	26,559	26,559	3,441	3,441
2	N. CA	MCDOT	10C0013	10C0013	CR 240B, Eel River Road	Eel River	6.2 m. N of Main St. (Potter Valley)	98.3		Joint Seal Repair/Replacement	18,383	20,000	1.09	17,706	44,265	2,294	5,735
* 3	N. CA	MCDOT	10C0070	10C0070	CR 306, Hearst Willits Road	Eel River	14.6 mi NE of Willits	43.8	SD	Joint Seal Repair/Replacement	6,142	20,000	3.26	17,706	61,971	2,294	8,029
4	N. CA	MCDOT	10C0081	10C0081	CR 429, Branscomb Road	South Fork Eel River	M.P. 10.5. 10.10 mi E of Hwy 1	87.5	SD	Deck Repair	4,071	173,415	42.60	153,524	215,495	19,891	27,920
5	N. CA	MCDOT	10C0082	10C0082	CR 429, Branscomb Road	Redwood Creek	M.P. 9.95, 0.5 mi E of Wilderness Lodge Rd	93.8	SD	Deck Repair	1,854	88,291	47.62	78,164	293,659	10,127	38,047

* This bridge is SD status with a 43.8 sufficiency rating. In the past, it was on the HBP nomination list to fund a painting project. Because of more critical situations elsewhere and very low traffic volumes (est <100 ADT), this bridge is unlikely to receive additional rehab or to be replaced in the foreseeable future.