PCC Rehabilitation Lessons Learned

RIGHT LANE
MUST
EXIT

Read my lips, replace concrete with concrete

DEC 18 2003

6D63565

SEP 20 2002

MAR 27 2003

FEB 10 2005


JUN 14 2005

FEB 10 2005

DEC 18 2003

DEC 18 2003

AUG 27 2002

26 1:26PM

JAN 13 2005


MAY 23 2002

JUL 12 2005

JUL 23 2003

MAR 25 2004


Designer decided to mill ac lip instead
of rehabilitating shoulder by cold planning
and overlaying. Fogseal will not cover
poor detail workmanship.

APR 6 2005

Technical Information

- Contact Trans-Lab
- Manual for slab replacement
- CD
- Contact Casey Holloway – Penhall
- Web site

http://www.dot.ca.gov/hq/esc/Translab/rpsc.htm