Caltrans | EXPLORATION BORING FIELD LOG | Date 12-18-07 | Boring No. DNB-R5

Location Doyle Drive Realignment | Lab No. | EA No. 163701 | Page 1 of 5

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Ft., Rt./Lt. | Line, Sta. | Northings. | Eastings. | Elev.

Ground Water Data: Date | Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : W Becker

Drill rig : Frontic Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion : 12-19-07

Depth	Sample Interval	Tool	Blows/ROD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1								← Drilled thru AC pavement	
2									
3			7						
			9	b					MC
4			9	a					Calibrating Energy
			5					← FILL - Poorly graded Silty Sand (SP)	
5			4					loose, dark brn, grey, moist, fine sand	SPT
			4					with gravel/g up to 1"	
6									
7									
			2						
8			2	b				← Poorly graded gravel (GP), loose,	MC
			1	a				dark grey, gravel/g 3/8" to 2"	
9								←	
10									Shelby - No processing
11									
12									
			1						
13			2	b					MC
			5	a					
14			4					← Poorly graded Silty Sand (SP-SM)	
15			11					medium/dense, dark grey, fine to medium	SPT
			11					Sand	
16									
17									
			14						
18			19						MC
			15	a					
19									
			4					← Same	
20			9						SPT
			19						
21									
22									

Caltrans | EXPLORATION BORING FIELD LOG | Date 12-18-07 | Boring No. DNB-R5

Location Doyle Drive Replacement | Log No. | EA No. 163701 | Page 2 of 6

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew :

Drill rig : Fratic Multidrill XL | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval / Tool	Blows / ROD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
22								
23		0					← Sandy lean Clay (CL), soft, dark gray, low to med. plasticity with marine shells	MC
		1					q_u = 0.5 Ton/ft²	
24		6	a					
		2					← Poorly graded silty Sand (SP-SM), med. dense? dark gray, fine to med Sand	SPT
25		6						
		19						
26								
27								
28		12						MC
		11						
29		14	a					
		3					← Same but dense and marine shells	SPT
30		12						
		21						
31								
32								
33		11						MC
		18						
34		32	a					
		13					← Uniformly graded Sand (SP), very dense?, dark brown, med. Sand (Colma Sand)	SPT
35		21						
		34						
36								
37								
38		20						MC
		27						
39		45	a					
		12					← Same	SPT
40		38						
		50	6"					
41								
42								

Caltrans | EXPLORATION BORING FIELD LOG | Date 12-18-07 | Boring No. DNB-R5

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 3 of 6

Dist. Co. Rt. P.M. Br. No. Purpose of Work

Ft., Rt. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew :

Drill rig : Fratic Multidrill XL | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval	Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description			Remarks
42												
43			26									MC
			46									
44			55	a								
			15						← Same			SPT
45			21									
			36									
46												
47												
48			26									MC
			37									
49			44	a								
			18						← Same			SPT
50			26									
			43									
51												
52												
53			20									MC
			28									
54			43	a								
			15						← Same, but dense			SPT
55			21									
			26									
56												
57												
58			13									MC
			36									
59			46	a								
			13						← Same			SPT
60			16									
			22									
61												
62												
63												

Caltrans — EXPLORATION BORING FIELD LOG — Date 12-5-07 — Boring No. DAB-KC3

Location: Dante Drive Replacement — Log No. — EA No. 167787 — Page 4 of 5

Dist. — Co. — Rt. — P.M. — Br. No. — Purpose of Work

Rt. — Ft., Lt. — Line, Sta. — Northings. — Eastings. — Elev.

Ground Water Data: Date / Time — Water Level — Bot. of Boring

Logged By: ED Tolan — Drill Crew:

Drill rig: — Hammer Type and Weight:

Drilling Method: — Casing:

Hole Completion:

Depth	Sampling Tool	Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
63									
		27						← Same	SPT
64		37							
		43							
65									
66									
67									
		27							MC
68		44							
		47	a						
69		12						← Lean Clay (CL), Hard, dark gray, low to med plasticity	SPT
		18						q_u = 3.5–4 Ton/ft²	
70		17							
71									
72									
		19							12-19-07
73		21	b						MC
		28	a						
74		13						← Same, but very stiff	SPT
		13						q_u = 1.25–1.5 Ton/ft²	
75		12							
76									
77									
		14							MC
78		16							
		21	a						
79		5						← Sandy lean clay (CL), very stiff low plasticity with marine shells	SPT
		6						q_u = 1.25–1.5 Ton/ft²	
80		10							
81									
82									
		14							MC
83		17							
		13	a						
84									

Caltrans — EXPLORATION BORING FIELD LOG — Date 12-17-01 — Boring No. DNF-05

Location Doyle Drive Replacement — Log No. — EA No. 16210 — Page 5 of 6

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings, Eastings, Elev.

Ground Water Data: Date / Time | Water Level | Hor. of Boring

Logged By: E. Ortega — Drill Crew:

Drill rig: J — Hammer Type and Weight:

Drilling Method: — Casing:

Hole Completion:

Depth	Sample No. and Type	Blows per 6"	Blows RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
24									
		5						← Same but very stiff	
25		8							
		22							
26									
27									
		18							
28		27							
		50	3.5"						
29		12						← Same but hard	
		17						q_u = 3.5 – 4.0 Ton/ft²	
30		22							
31									
32									
		17						← Same	
33		26							
		40							
34									
35									
36									
37									
		20						← Same	
38		31						q_u > 4.5 Ton/ft²	
		45							
39									
40									
41									
42									
43									
		20						← Same (with coarser sand)	
44		34							
		44							
45									
46									
47									
48									
49									
50									
51									

Caltrans

EXPLORATION BORING FIELD LOG

Date 12-11-07 | Boring No. VNF7-B3

Location | Log No. | EA No. 15-2161 | Page 6 of 6

Dist. Co. Rt. P.M. Br. No. Purpose of Work

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : | Drill Crew :

Drill rig : | Hammer Type and Weight :

Drilling Method : | Casing :

Hole Completion :

Depth	Sample Interval	Log	Blows /ft	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
111									Change of soil @ 111
112			24					SEDIMENTARY ROCK (SHALE) dark, gray, very intensely fracture to decomposed, soft, wet/heated	
113			39						
114			50	5"				Clean Clay (CL), low plasticity	
								Bottom of Boring @ 114' on 12-11-07	

DNB-RG

Caltrans

EXPLORATION BORING FIELD LOG

Date 1-08-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 1 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft.. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : R Medina

Drill rig : Fraste Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion :

Depth	Soil Type & Consistency	Blows per 6" / Blows per foot	RQD	Sample I.D.	% Rec.	Structure	Graphic Log	Description	Remarks
1								← Drilled through AC pavement	
2									← Fill
3									
4									
5								← Poorly graded Silty Sand (SP), very loose, dark gray, wet, sand,	MC
6		0	a					with marine shells, weak cementation, over	← Clay
7								Sandy Clay (CH) very soft, dark gray,	
8								wet & high plasticity.	
9								(12" SP over 6" CH)	
10									Shelby
11									
12									
13		50	per 1"						← Sand
14									
15		3							
16		4							MC
17		12	a						
18		8						← Poorly graded Silty Sand (SP), med.	
19		11						dense, dark gray, wet, sand, with	SPT
20		17						marine shells, weak cementation.	
21									
22		15							
23		23							MC
24		27	a						
25		6							
26		10						← Same	SPT
27		11							
28									
29									
30		1							MC
31		3							
32		13	a						

DNB-R6

Caltrans EXPLORATION BORING FIELD LOG

Date 1-08-08 | Boring No.

Location Davie Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 4

Dist. 09 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings, Eastings, Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : R Medina

Drill rig : Fraste Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion :

Depth	Sample Interval	Blows/ Foot	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
27		3					← Same but dense.	SPT
		12						
28		21						
29								
30		3						
		3						
31		6	a					
32		3					← Same but med. dense	
		11						
33		17						
34								
35		9						
36		22						
		23	a					
37		10					← Coarse Sand: Poorly graded Silty Sand (SP), dark Brown, well sand, weak cementation and some oxidation spots	
		18						
38		24						
39								
40		14						
41		30						
		38	a					
42		8					← Same but very dense	
		19						
43		38						
44								
45		33						
46		31						
		42						
47		10						
		21						
48		38						
49								
50								
		12					← Same but dense	
		18						
51		24						

DNB-R6

Caltrans

EXPLORATION BORING FIELD LOG

Date 1-08-08 | Boring No.

Location: Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 3 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work: Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By: E Ortega | Drill Crew: R Medina

Drill rig: Fraste Multidrill XL | Hammer Type and Weight:

Drilling Method: Wet Rotatory | Casing:

Hole Completion:

Depth	Sample No. and Interval	Blows/6"	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description			Remarks
58											
59											
60											
61											
62		10						← Sand, brown, med. dense and			SPT
63		12						dark grey			
64		14									
65											
66											
67											
68											
69											
70											
71		9						← Same			SPT
72		11									
73		18									
74											
75											
76											
77											
78											
79											
80											
81											
82											
83											
84											
85											
86		10						← Same			SPT
87		14									
88		19									
89											
90											
91											← Clay
92											
93											Shelby
94											
95											
96											
97											
98											
99											
100											
101											
102											
103											
104											
105											
106		6						← Sandy fat Clay with gravel			SPT
107		7						to ¼" (CL) Very stiff, moist to high plas			
108		10						Q = 4.5 Tsf/ft²			
109											
110											
111											
112											

DNB-R6

EXPLORATION BORING FIELD LOG

Caltrans

Date 1-9-08 | Boring No.

Location Doyle Drive Replacement | Log No. | EA No. 163701 | Page 4 of 4

Dist. 04 Co. SF Rt. 101 P.M. | Br. No. | Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. | Line, Sta. | Northings, | Eastings, | Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E. Ortega | Drill Crew : R Medina

Drill rig : Frasto Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion :

Depth (ft)	Sample Type (Soil) / Blow Count (Rock)	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description		Remarks
80	50/2"						← SEDIMENTARY ROCK (Sandstone), olive yellow, moderately to slightly fractured moderately soft, slightly weathered healed with Clay		SPT (2") Cored 80'2" to 85' Munsell Hue 5Y 6/6 Time 8:03 - 9:19
81							RQD = 9+15+17+16/60 = 85%		
82									
83									
84									
85							← Same		
86							RQD = 7+5.5+9.25+13.5+15+5 / 60	82%	Time 9:38 - 9:57
87									
88									
89									
90							← Same but very intensely fractured		Time 10:09 - 10:35
91									
92									
93									
94									
95							← Shale, bluish gray, very intensely to intensely fractured moderately soft, slightly weathered healed with clay		Time 10:46 - 11:03 Munsell Chart 2 for Gley 5/1
96									
97									
98							Bottom of Boring @ 98' on 1-09-08		

DNB-R7

Caltrans | EXPLORATION BORING FIELD LOG | Date 1-9-08 | Boring No.

Location: Doyle Drive Replacement | Log No. | EA No. 163701 | Page 3 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work: Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time / Water Level / Bot. of Boring

Logged By: E Ortega | Drill Crew: R Medina

Drill rig: Fraste Multidrill XL | Hammer Type and Weight:

Drilling Method: Wet Rotatory | Casing:

Hole Completion:

Depth	Sample No. and Type	Blows/6" or RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
52		10 17 25					← Same but denser	SPT
53								
54								
55		9 14 21					← Same but dark gray	SPT
56								
57								
58								
59								
60		9 12 15					← Sandy lean clay (CL) very stiff, dark gray, low plas. τ_p = 11.0 Tsf/ft²	SPT
61								
62								
63								
64								
65								
66		14 13 13					← Same τ_p = 4.25 Tsf/ft²	SPT
67								
68								
69								
70								
71								Shelby (Picture) silt with rock fragments to 1"
72								
73								
74								
75		40 50 1"					← SEDIMENTARY Rock (Sandstone) pale olive, moderately to slightly fractured, soft, slightly weathered healed with clay RQD = 22+8.5/32 = 95.3%	← Rock SPT Cored 75'7" – 78' 1-10-08 Munsell Hue 5Y 6/4
76								
77								
78								

DNB-R7

Caltrans EXPLORATION BORING FIELD LOG

Date 1-9-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 2 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Ft.. Rt. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E. Ortega | Drill Crew : R Medina.

Drill rig : Fraste Multidrill XL | Hammer Type and Reloff :

Drilling Method : Wet Rotatory | Casing :

Hole Completion :

Depth	Sampled Interval	Blows/6" Local	Blows/6" RAD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
27		3						Lean Clay with sand (CL), stiff, dark gray, low plas.	SPT
28		4							
29		6							
30									
31									
32		4							MC
33		4							
34		4	a						
35		4						Poorly graded sand with clay (SP-SC), med dense, dark gray, med sand with marine shells	SPT
36		4							
37		7							
38									
39									
40		9							MC
41		12							
42		33	a						
43		7						Colma Sand, poorly graded Sand (SP), dense, reddish brown, med sand, with oxidation spots weak cementation.	SPT
44		13							
45		21							
46									
47									
48		16							MC
49		26							
50		40	a						
51		14						Same but very dense	SPT
52		34							
53		40							
54									
55									
56		20							MC
57		30							
58		40	a						
59		12						Same	SPT
60		27							
61		42							
62									
63									
64		20							MC
65		29							
66		35	a						

DNB-R7

Caltrans EXPLORATION BORING FIELD LOG

Date 1-09-08 | Boring No.

Location Doyle Drive Replacement | Loc No. | EA No. 162701 | Page 1 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft. Lt. Line. Sta. Northings. Eastings. Elev.

Ground Water Data: Date / Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : R Medina

Drill rig : Fraste Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotatory | Casing :

Hole Completion : 1-10-08

Depth	Sample Interval	Lost Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description	Remarks
1								Drilled thru AC Pavement.	
2								Sand and Bay Mud	
3									← Sand
4									← Bay Mud
5									
6		1						← Fat Clay with sand (CH), soft	MC
		1						dark gray, med to high pls	
		2	a						
7									
8									
9									Shelby
10									
11									
12		1						← Poorly graded, Silty Sand (SP),	SPT
		4						med dense, dark gray, med sand,	
14		9						weak cementation	
15									
		9							MC
16		11							
		30	a						
17		5						← Same	SPT
		12							
18		16							
19									
20									
		13							MC
21		16							
		13	a						
22		5						← Same but dense and with	SPT
		14						marine shells	
23		17							
24									
25									
		1							MC
26		0							
		2	a						

DNB-R7

EXPLORATION BORING FIELD LOG

Caltrans

Date 1-10-08 | Boring No.

Location Doyle Drive Replacement | Lab No. | EA No. 163701 | Page 4 of 4

Dist. 04 Co. SF Rt. 101 P.M. Br. No. Purpose of Work Geotechnical Investigation

Rt. Ft., Lt. Line, Sta. Northings, Eastings, Elev.

Ground Water Data: Date/Time | Water Level | Bot. of Boring

Logged By : E Ortega | Drill Crew : R Medina

Drill rig : Frasto Multidrill XL | Hammer Type and Weight :

Drilling Method : Wet Rotetary | Casing :

Hole Completion :

Depth	Soil Classification	Log of Blows	RQD	Sample I.D.	% Rec.	Strength	Graphic Log	Description			Remarks
70								← Same			
71								RQD = 23+13.5+12.5+4.5/58 = 92.2%			
72											
73											
74								← Same but intensely to			
75								very intensely fractured			
76								RQD = 11+9.5+10+5.5+6.5+5+4.5/62 = 83.9%			
77											
78											
79								← Shale, bluish gray, slightly to			Munsell 2.5 for Gley 5/1
80								moderately fractured, moderately soft			
81								moderately weathered,			
82								healed with Clay			
83								RQD = 7.5+11.5+12.5+8+13.5+6/60 =	78.5%		
84								← Same but intensely to very intensely			
85								fractured			
86								RQD = 15.5+7+6.5+5/53 = 64.1%			
87											
88								← Bottom of boring @ 97.5			
89								on 1-10-08			
90											