STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION

Form HC-10A (Rev. 6/80)

Job Stamp
04-0120F4
SFOBB SAS

Report No. 392

Date **01/09/08**

Shift Hours Start 0700 Stop 1530

ASSISTANT RESIDENT ENGINEER'S

BI-131 Photo Survey Of Existing Facilities by Municon Consultants

EQUIPMENT AND/OR LABOR:

Equip. #	NO. MEN	DESCRIPTION (Of Equipment or Labor)	HOURS - ITEM NO. BI-131 Pre-Const. Survey									IDLE OR DOWN	REMARKS Name	Contractor
	1	CMI (With Still Camera)	2										Walter R. Badertscher	ABF/Municon Consultants
	1	(With VHS Video Camera)	2										Emaneab Hailezhi	ABF/Municon Consultants
	1	Small pickup Truck	2											ABF/Municon Consultants

Date: 01/09/08, Wednesday

Weather: Rain/Cloudy, Temp: Max 50°F and Min 43°F

Description of Operation: Darryl Schram, Frances and I visited the site to help the photo survey team from Municon Consultants and opened the building No. 262 for internal photograghy and physical check up of the building. The photo survey team visited the site and took photographs of the interior of the building. There were crack monitoring gauges installed at various places where there were cracks in the vertical walls. The building was empty except some empty enclosures. The top shingle roof was broken at places.

Note:

Inspector:

Mohinder Chahal

46.002