STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
CP-CEM 4601 (Rev. 4/99) (Old HC-10A)

TOLL PROGRAM/DIST. 4 CONSTR.

Job Stamp:
04-SF-80-13.2/13.9 04-0120F4
SFOBB SAS
San Francisco Co. in San Francisco
Fm 0.6 km to 1.3 km East of Yerba Buena
Tunnel East Portal

Report No. **46.B**

Date the Shift Began: 6/2/08

☐ NIGHTWORK MONDAY

Shift Hrs	Start	6:30	Stop	14:30
Engineer's Hrs	Start	13:00	Stop	17:30

ASSISTANT RESIDENT ENGINEER'S DAILY BRIDGE REPORT

Location: Remark:	7-day const. cal.: 537 Project work day: 747	Weather: Windy - Sunny

Description of Operation:

			HOURS - ITEM NO.								
		ITEM NO. >>	38								
			Structural Concrete, Bridge						IDLE OR DOWN/ ELSEWHERE		
EQUIPMENT AND/OR LABOR:											
EQPT. NO.	NO. MEN	DESCRIPTION (Of Equipment or Labor)	RT	RT					< RT/OT		

Prime	American Bridge / Fluor JV	(P)
Sub #1		(1)
Sub #2		(2)
Sub #3		(3)
Sub #4		(4)
Sub #5		(5)

REMARKS Name	Classification	Prime / Sub

Finally, the wait was over as the cap beams and a few of the bracing elements (HSS 10x10x1/2") arrived at the job site today. This work was observed by Massoud.

I came to work right after lunch today and as such missed our staff meeting. I had a Dr's appointment at 11:30 this morning.

Upon arrival at the office, I began reviewing Submittal 380, which discusses E2 X-beam ISDs. In turn, this Submittal discusses RFIs 778, 958, 959, 960, 961, 962, 963, 964, and 967. Therefore, Massoud & I were discussing all these documents in relation to the plan sheets.

Materials:

Insp. Hrs.	
REG: 5.0	INTERMITTENT INSPECTION
OT 0.0	

REC'D '08 JUN 20 A 005430

Saman Soheili — Assistant Structure Rep.
Saman Soheili — Title