STATE OF CALIFORNIA – DEPARTMENT OF TRANSPORTATION

RESIDENT ENGINEER'S DAILY REPORT
ASST. RESIDENT ENGINEER'S DAILY REPORT

DC-CEM-4501-CUSTOM

RESIDENT ENGINEER'S DAILY REPORT – FILE CAT. 45 [ ]

ASST. RESIDENT ENGINEER'S DAILY REPORT – FILE CAT. 46 [X]

JOB STAMP

04-0120F4
04-SF-80-13.2/13.9
SAS

REPORT NO.: **592 to 598**	DATE: **07/27/08 to 08/02/08** M T W T F S S (Circle Day)
SHIFT HOUR: START; **07:30** STOP; **16:00**	TEMPERATURE: MIN; **NA** MAX; **NA**

WEATHER:

(NA – See Weakly Statement of Working Days)

Sunday:
- No Activity.

Monday:
- Bereavement Leave.

Tuesday:
- Go out to the jobsite to monitor Dutra to install coffer cell and turbidity curtain at bent C5-8.
- Checking and reply emails.
- Prepare Asst. Resident Engineer's Daily Report and Jobsite Diary Report.

Wednesday:
- Go out to the jobsite to monitor Dutra to install coffer cell at bent C5-8.
- Do Weekly SWPPP Inspection with Branden Bedwell, and Courtney Cacace. (See PMIV Cat.20.05 for Attachment H Report.)
- Fill out SWPPP Attachment H Reports.
- Checking and reply emails.
- Prepare Asst. Resident Engineer's Daily Report and Jobsite Diary Report.

Thursday:
- Go out to the jobsite to monitor Dutra to fill in the rock at bent C5-8.
- Review SWPPP Amendment #13.
- Checking and reply emails.
- Prepare Asst. Resident Engineer's Daily Report and Jobsite Diary Report.

Friday:
- Go out to the jobsite to monitor Dutra to install turbidity curtain at bent C1-4.
- Review SWPPP Amendment #11, Rev.01, Amendment #12 and #13.
- Checking and reply emails.
- Prepare Asst. Resident Engineer's Daily Report and Jobsite Diary Report.

Saturday:
- No Activity.

SIGNATURE **(Robert Wong)**	TITLE **T.E & Office Engineer, SAS**

REC'D 08 OCT 06 R006816