STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION

Form HC-10A (Rev. 6/80)

Job Stamp
04-0120F4
SFOBB SAS

Report No. 638

Date **09/11/08**

Shift Hours Start 0700 Stop 1530

ASSISTANT RESIDENT ENGINEER'S BI#132 Vibration Monitoring

EQUIPMENT AND/OR LABOR:

Equip. #	NO. MEN	DESCRIPTION (Of Equipment or Labor)	HOURS - ITEM NO. BI#132	BI#131								IDLE OR DOWN	REMARKS Name	Contractor

Date: 09/11/08, Thursday

Weather: Clear. Temp: Max 68°F and Min 56°F

Description of Operation: Observation of Construction activities around Torpedo Building No. 262.

Note: Visited building No. 262 (Torpedo Building) and observed that installed crack monitoring gauges outside the building by Municon Consultants was in place. Drilling was going on CDIH Pile C3 and has reached almost the full depth. No light was observed on the light-omitting sensor. Bryan O'Sullivan was supervising the drilling operation at these CDIH piles. He informed that during drilling operation he did not see light on the light-emitting sensor during this operation.

Inspector:

Mohinder Chahal 9/18/2008

RECD *08 OCT-07 #007037

PS