STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
CP-CEM 4601 (Rev. 4/99) (Old HC-10A)

TOLL PROGRAM/DIST. 4 CONSTR.

Job Stamp:
04-SF-80-13.2/13.9 04-0120F4
SFOBB SAS
San Francisco Co. in San Francisco
Fm 0.6 km to 1.3 km East of Yerba Buena
Tunnel East Portal

Report No.

7-day const. cal.: 609
Project work day: 819

Date the Shift Began: 8/13/08

☐ NIGHTWORK WEDNESDAY

Shift Hrs	Start	6:30	Stop	15:00
Engineer's Hrs	Start	6:30	Stop	15:00

ASSISTANT RESIDENT ENGINEER'S DAILY BRIDGE REPORT

Location: E2 Cross Beam Remark: sandblast/flashing		Weather: clear Hi 87F/Lo 58F

Description of Operation:
ABF - continue to sandblast column cages free of zinc coating at E2E/continue to lay flashing (tin) down at panel edges

HOURS - ITEM NO.							
ITEM NO. >>	38	48					IDLE OR DOWN/ ELSEWHERE
	Structural Concrete, Bridge	Bar Reinforcing Steel (Bridge)					
	RT	RT					< RT/OT

EQUIPMENT AND/OR LABOR:

EQPT. NO.	NO. MEN	DESCRIPTION (Of Equipment or Labor)

CONTRACTORS

Prime	American Bridge / Fluor JV	(P)
Sub #1		(1)
Sub #2		(2)
Sub #3		(3)
Sub #4		(4)
Sub #5		(5)

REMARKS

Name	Classification	Prime / Sub

For equipment and personnel hours, please see MASOUD MADANLOU'S diaries.

Weekly meeting with ABF today: ABF will be working 10 hr days/8hr Saturday until the concrete pour at W2 (Aug 21st).

ABF contined to sandblast the column cages at the south end of the cross beam (E2E).
They continue to place tin flashing down at the panel edges.

More time spent on my part reading plans/RFIs/Submittals for E2

Materials:

Insp. Hrs.	
REG: 8.0	INTERMITTENT INSPECTION
OT:	

REC'D 08 OCT 08 #007126

DAVID CHUNG — TE/CT
Title