



Daily Update

May 1

Geological Work

Devil's Slide (post mile 39.14)

- Drilling for the third inclinometer is complete. Inclinometers will now be monitored to establish the rate at which the slide is moving.
- Various repair designs are being developed and evaluated while data from the inclinometers is being gathered.
- Geologists report that visual observations indicate slide movement has slowed considerably. However, data from the inclinometers is needed before a quantitative assessment can be made.

Repair Work

Slide at Post Mile 40

- Repair work continued today. Reconstruction of the embankment is due to be complete by the end of the week.