



Daily Update

May 5

Geological Work

Devil's Slide (post mile 39.14)

- Slope inclinometers are read each day. The measurement information is used in developing the repair design.

Repair Work

Devil's Slide (post mile 39.14)

- Crews installed metal posts on the cliff side below the roadway. The posts support the debris fence that will prevent material from repair work falling further down the cliff.

Slide at Post Mile 40

- Restriping the road, erosion control and planting on slopes above and below the road remain to be done. A drain along the southbound shoulder will be installed Saturday.